

2005 CASE 570MXT INDUSTRIAL LOADER

INSPECTION DETAILS

| | |
|-------------------|----------------------------------|
| Inspection Type | Consignment |
| Inspection Form | Standard |
| Inspection # | 10223208 |
| Inspection Status | Inspected |
| Created | 08/13/25 22:25:19 |
| Updated | 08/14/25 00:43:06 |
| Created By | Gabriel, James P. |
| Inspector | Gabriel, James P. |
| Serial # | JJG0302653 |
| SMU / Hours | 6,313 |
| Location | Brawley, CA 92227, United States |



FEATURES

General

- **Drag Box**
Woods Gannon 84" with ripper
- **Drive - 4 Wheel**
- **Lighting**
- **ROPS - Open**

Regulatory

- **Emissions Level**
2005 US EPA

Attachments

- **Bucket, MP**

NOTES

Actual hours unknown. Meter shows 3112 but filters marked with 6282 Hours.

CONDITION

●●● Good

●● Fair

● Poor

Approved Repair

GENERAL APPEARANCE

Cab or Canopy

●●●

Canopy

Counterweight

●●●

Crankcase Guard / Battery Box

●●●

Differential Supports

●●●

Eng. Enclose Hood / Stack

●●

●3

Fenders

●●●

Left side of hood is bent and missing lift handle. Hood is difficult top open and close.

Fuel Tank

●●●

Grab Irons

●●●

Main Frame Welds

●●●

Paint

●●

Paint is faded.

Radiator Grill & Shroud

●●●

Steps / Ladder

●●

●1

Right cab step is bent.

Cleaning Required

YES

Machine needs cleaned.

S.O.S. Taken

YES

Engine

SAFETY ITEMS

Horn

●

Horn inoperative.

Loader frame lock

●●

●1

Has incorrect bolt on loader frame lock bar.

ROPS

YES

Safety Decals In Place

YES

Safety Decals Legible

YES

OPERATOR STATION

Dash Console



Front console is broken all around glove box. Right instrument panel is missing all screws.



3

Floor Boards



Gauges



Lens cluster is scratched and gauges difficult to read.

Glass/Mirrors



Rear view is missing glass.



1

Meter



3112 Hours

Seat Belt



Seat Cushion / Arm Rest



Switches



Back Up Alarm

YES

Alarm is inoperative

Current O&MM

NO

Current Safety Manual

NO

ROPS Certification Plate

YES

Fuel Level

90%

ENGINE

Air Cleaners



Belts / Pulleys - ENGINE



Belt is cracked.



2

Engine Supports



Exhaust / Muffler



Fuel Injection System



Fuel prime pump is missing plunger handle.



1

Governor



Operating Condition - ENGINE



Turbocharger / Blower



Blow By

NO

Compression in Radiator

NO

Emissions Decal

NO

Fluid Levels OK?

YES

Knocking

NO

Oil Leaks

NO

Water in Oil
NO

Anti-Freeze Color
Clear coolant level is a little low.
Overflow bottle missing a cap.

Oil Pressure (H/L/N)
Normal

Smoke (B/D/L/W)
Normal

COOLING SYSTEM

Coolers

Fan

Fan Drive

Hoses

Radiator

Water Pump

Leaks - COOLING SYSTEM
NO

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator

Batteries / Cables

Lighting



Starter

Wiring



Has some wires hanging from left rear
of machine near transmission filter

Ether Aid
NO

Warning Lights
YES



Left side lenses cracked.

TRANSMISSION

Case

Controls

Cooler

Lines / Fittings - TRANSMISSION

Operating Condition -
TRANSMISSION

Seals



Transmissio has some oil residue
needs cleaned and checked for
possible leak.

Temp / Pressure Gauges



Torque Converter



Transmission - Forward Shifts



Transmission - Reverse Shifts



Transmission - Type



Universal Joints



Four sped manual with shuttle lever.

Transmission - Noisy

NO

STEERING

Front Axle - STEERING



Front axle center pin and bushing worn and loose.



Hand Metering Unit



Lines / Fittings - STEERING



Steering Cylinder



Steering Valves / Pumps



Tie Rods / Rod Ends



Inner tie rods have some play.

BRAKE

Brake Linkage



Parking Brake



Pedal



Fluid around brake pedals.

Leaks - BRAKE

YES

See pedal

HYDRAULICS

Bucket & Hoist Kickout



Tilt return to dig is inoperative.

Hose Lines



Lift cylinder lines are weathered and outer layer is cracked.



Lift Cylinders



Overall Operating Condition -
HYDRAULICS



Due to a few leaks.

Pumps & Valves



Tilt Cylinder



ATTACHMENTS / WORK TOOLS**Gannon**

84IN with ripper

Gannon cutting edges.

Router bits on sides of box are worn

2**Gannon cylinders.**

Gannon tilt cylinder is seeping oil.

2**Gannon pins and bushings**

Pins and bearings worn on linkage and cylinder mounts.

4**BUCKET****Bucket Bottom****Bucket Floor****Bucket Sides****Cutting Edges****Loader Frame****Loader Pins & Bushings**

Loader frame and bucket pins and bushings are worn and loose.

Multi Purpose Cylinders**Quick Attach****NO****Bucket Capacity**

1.1YD

Bucket S/N

no tag

FINAL DRIVES**Differentials****Front Axle - FINAL DRIVES****Front Final Drives****Rear Axle****Rear Final Drives****Wheel Lugs & Rims**

Leaks - FINAL DRIVES
NO

TIRES

| | Make / Serial# | Tread Depth in 1/32" | % Life Remaining | Recapped | Tread Cuts/Chunks | Side Cuts Section |
|-------------|----------------|-------------------------|---------------------|-----------|----------------------|----------------------|
| Left Front | Samson | 18 | 64.20 | NO | NO | NO |
| Left Rear | Prostar | 5 | 17.86 | NO | YES | NO |
| Right Front | Samson | 15 | 53.57 | NO | NO | NO |
| Right Rear | Prostar | 6 | 21.43 | NO | YES | NO |

Average Life Remaining - TIRES
39.29

Tire Size - TIRES
Front 12-16.5 Rear 19.5L24

MARKETING PHOTOS (29)









