

2020 CAT 14015 MOTOR GRADERS

INSPECTION DETAILS

Inspection Type	Marketing
Inspection Form	Standard
Inspection #	10210754
Inspection Status	Completed
Created	06/19/25 18:19:38
Updated	07/07/25 10:22:20
Created By	Garcia, Jr
Inspector	Garcia, Jr
Reviewers	Calderas, Marco
Salesperson	Schultis, Derrick R.
Stock #	E205360
Serial #	EB200214
SMU / Hours	7,518
Location	Eloy, AZ, United States



FEATURES

General

- Air Conditioner
- Differential Lock
- Lighting
- Pushblock
- ROPS - Enclosed
- Air Suspension Seat
- Drive - Tandem
- Mirrors
- Radio
- Throttle Lock
- Defroster Fan
- Guard, Transmission
- Moldboard Size - 14'
- Ripper - Multi-Shank
- Tire Size

Regulatory

- Ultra Low Sulfur Diesel Fuel

CONDITION

●●● Good

●● Fair

● Poor

Approved Repair

GENERAL CONDITION

Body
●●●

Frame - GENERAL CONDITION
●●●

General
●●●

ET Product Status Report
Download
YES

Logged / Active Codes
YES

Machine Starts and is Operable
YES

Tires are Aired Up and Drivable
YES

GENERAL APPEARANCE

Battery Box
●●●

Cab or Canopy
●●●

Crankcase Guard / Transmission
Guard
●●●

Decals
●●●



Draw Bar
●●●



Engine Enclosures
●●●



Missing decals on left and right rear
sections of engine compartments

Left rear section has damaged screen

Front Frame Welds
●●●

Fuel Tank
●●●

Grab Irons
●●●

Hood
●●●

Radiator Grill
●●●

Rear Frame Welds
●●●

Sheet Metal
●●●



Left rear step on tandem housing is
bent

Steps / Ladder
●●●



Horn
●●●

SAFETY ITEMS

Back Up Alarm
●●●

Camera(s)
●●●

ROPS



Seat Belt / Date



May 2025

1

Secondary Exit



Parking Brake Functioning

YES

ROPS Certification Plate

YES

Safety Decals In Place

YES

Safety Decals Legible

YES

Safety Locks / Pins

YES

Service Brakes Functioning

YES

OPERATOR STATION

Air Conditioner



Ambient temp at 101.8F and vent temp at 47.7F

1

Armsrests



Dash Console



Door Latches / Hinges / Seals



Floor Boards / Mats



Gauges



Headliner



Heater / Defroster



75 ambient temp and 103 vent temp

Hour Meter - GAUGES, OPERATION STATION, CONSOLE



Hydraulic Controls



Interior Lights



Interior Plastic / Fabric



Mirrors



Monitoring Display



Pans/Guards



Radio



ANTENNA IS BENT AND DAMAGED

1

Seat Cushions / Suspension / Type



Switches



Transmission Controls



Visor / Sunshade



Windows



Windshield Wipers



ENGINE

Belts / Pulleys - ENGINE


Engine Oil Level / Condition


Engine Supports / Mounts


Exhaust / Muffler / Stack


Fuel Injection System


Governor


Intake / Air Filters


Operating Condition - ENGINE


Turbocharger / Blower


Blow By
NO

Fuel Leaks
NO

Knocking
NO

Oil Leaks
NO

Service Needed
YES

Water in Oil
NO

Oil Pressure (H/L/N)
Normal

Smoke Color (B/D/L/W)
Normal

EMISSIONS

Aftertreatment Heat Shields /
Guards


DEF Lines / Wiring


Diesel Particulate Filter (DPF)
Condition / Service Hours


Aftertreatment System Codes
NO

Leaks / Type
NO

COOLING SYSTEM

Anti-Freeze Level / Color /
Condition


Belts / Pulleys - COOLING
SYSTEM


Coolers


Fan


Fan Drive / Type


Hoses / Tubes


Radiator



Water Pump



Compression in Radiator

NO

Coolant Leaks

NO

Oil in Anti-Freeze

NO

Standard Radiator

YES

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator



Batteries / Cables



Starter



Wiring



Work Lights



3

Jump Start Terminal

YES

Signal Lights

YES

TRANSMISSION

Case - TRANSMISSION



Controls - TRANSMISSION



Cooler



Operating Condition -
TRANSMISSION



Transmission - Forward Shifts



Transmission - Reverse Shifts



Transmission Oil Filter Condition
/ Service Hours



Powershift

YES

Transmission - Noisy

NO

STEERING

Articulate P & B



King Pins



Lines / Fittings



Steering Cylinder



Both rear steering cylinders have movement at pins and bushings.



Steering Frame



Steering Operating Condition



Steering Pump



Steering Linkage



Tie Rods / Rod Ends



Wheel / Joystick



Steering Valve



Joystick

Wheel Lean Cylinder - STEERING



BRAKE

Control Valve



Lines



Parking Brake Operation



Pedal



Service Brake Operation



DRIVECHAIN / TANDEMS

Differential



Differential Lock / Operation



Drivetrain / Tandem Leaks



Leaks

Oscillating Hubs / Oil Level



Planetary



Tandem Housing / Drive Chains



Wheel Lugs & Rims



HYDRAULICS

Blade Cushion



Circle Drive Box



Circle Side Shift Cylinder



Cylinder Mounts / Pins



Has movement



Hydraulic Lines / Fittings



Hydraulic Pump



Has wet lines under front cover.

Hydraulic Valves



Lift Cylinders



Linkage



Pump Drive Shaft



Saddle Pin / Actuator



Side Shift Cylinder



Has oil residue at hoses.

Tank / Sight Glass / Cap



Tip Cylinder



Leaks - HYDRAULICS

NO

Notes - HYDRAULICS



HAS LOOSE GREASE LINE NOT
HOOKED UP ON CIRCLE

BLADE

Circle A Frame



Circle Frame



Circle Shoes / Inserts



Worn

Cutting Edge



Cylinder Balls / Caps



Face / Moldboard



Frog / Base Edge



Moldboard Tip Brackets / Inserts



Ring Gear



Saddle



Tip Bracket Pivots / Bearings



RIPPER

Beam



Brackets / Studs



Cylinders



Trunnion mounts have movement

Frame



Lines / Fittings - RIPPER



Pins / Bushings



Shanks / Ripper (GET)



Worn



Shanks / Scarifier (GET)



Worn. Missing 4 shanks



TIRES

	Make / Serial#	Tread Depth in 1/32"	% Life Remaining	Recapped	Tread Cuts/Chunks	Side Cuts Section
Left Center	Condor	19	54	NO	YES	YES
Left Front	Tiron	21	52	NO	YES	YES
Left Rear	Ceat	16	47	NO	YES	YES
Right Center	Condor	12	18	NO	YES	YES
Right Front	Michelin	8	14	NO	YES	
Right Rear	Ceat	18	51	NO	YES	YES


Radial
YES

Average Life Remaining - TIRES
40%

Notes - TIRES
Left rear missing lug bolt
QUOTED ABOVE

 1 Tire Size - TIRES
17.5R25


MARKETING PHOTOS (29)













LINE ITEM PHOTOS (53)

Logged / Active Codes

YES



Decals



Missing decals on left and right rear sections of engine compartments



Draw Bar



Engine Enclosures



Left rear section has damaged screen



Sheet Metal



Left rear step on tandem housing is bent



Camera(s)



Seat Belt / Date



May 2025



Air Conditioner



Ambient temp at 101.8F and
vent temp at 47.7F



Heater / Defroster



75 ambient temp and 103 vent
temp



Radio




ANTENNA IS BENT AND
DAMAGED




Current O&MM

YES




Current Safety Manual

YES



Work Lights



Steering Cylinder



Both rear steering cylinders have movement at pins and bushings.



Drivetrain / Tandem Leaks

Leaks




Cylinder Mounts / Pins

Has movement



Hydraulic Lines / Fittings


Has wet lines under front cover.



Side Shift Cylinder



Has oil residue at hoses.



Circle Shoes / Inserts



Worn



Cylinders



Trunnion mounts have movement



Shanks / Ripper (GET)



Worn



Shanks / Scarifier (GET)



Worn. Missing 4 shanks



Notes - HYDRAULICS

HAS LOOSE GREASE LINE NOT
HOOKED UP ON CIRCLE



Make / Serial#	Tread Depth in 1/32"	% Life Remaining	Recapped	Tread Cuts/Chunks	Side Cuts Section
Left Center	Condor	19	54	NO	YES
					
					
Make / Serial#	Tread Depth in 1/32"	% Life Remaining	Recapped	Tread Cuts/Chunks	Side Cuts Section
Left Front	Tiron	21	52	NO	YES
					



Make / Serial#	Tread Depth in 1/32"	% Life Remaining	Recapped	Tread Cuts/Chunks	Side Cuts Section
Left Rear	Ceat	16	47	NO	YES



Make / Serial#	Tread Depth in 1/32"	% Life Remaining	Recapped	Tread Cuts/Chunks	Side Cuts Section
Right Center	Condor	12	18	NO	YES
					

Make / Serial#	Tread Depth in 1/32"	% Life Remaining	Recapped	Tread Cuts/Chunks	Side Cuts Section
Right Front	Michelin	8	14	NO	YES
					



Make / Serial#	Tread Depth in 1/32"	% Life Remaining	Recapped	Tread Cuts/Chunks	Side Cuts Section
Right Rear Ceat	18	51	NO	YES	YES



Notes - TIRES

Left rear missing lug bolt

QUOTED ABOVE

