



2010 CAT
994F
WHEEL LOADER

INSPECTION DETAILS

Inspection Type	Consignment
Inspection Form	Wheel Loaders
Inspection #	10220939
Inspection Status	Inspected
Created	08/05/25 09:17:11
Updated	08/09/25 21:49:04
Created By	Akutey, Solomon
Inspector	Akutey, Solomon
Reviewers	Akutey, Solomon
Serial #	44200304
SMU / Hours	43,050
Location	Mexico



FEATURES

General

- Air Conditioner
- Counterweight
- Engine Enclosures
- Lighting
- Steering Type - Joystick
- Auto Shift
- Coupler - Standard
- Fire Extinguisher
- Mirrors
- Boom, GP
- Coupler Type - Mechanical
- Lift - High
- ROPS - Enclosed

Regulatory

- Ultra Low Sulfur Diesel Fuel

Technology

- Vital Information Management System (VIMS)

Attachments

- Bucket

CONDITION

Good

Fair

Poor

Approved Repair

GENERAL APPEARANCE

Battery Compartment	Cab / Canopy	Counterweight
<div><div></div><div></div><div></div></div>	<div><div></div><div></div><div></div></div>	<div><div></div><div></div><div></div></div> <div>Faded paint and scratches on the edges</div>
Engine Enclosure Panels	Fenders	Front Frame
<div><div></div><div></div><div></div></div>	<div><div></div><div></div><div></div></div>	<div><div></div><div></div><div></div></div> <div>Clean for thorough inspection</div>
Fuel Tank	Grab Handles / Handrails	Hood Panels
<div><div></div><div></div><div></div></div>	<div><div></div><div></div><div></div></div>	<div><div></div><div></div><div></div></div> <div>Dents/bent few ones</div>
Paint & Decals	Platforms	<div><div></div><div></div><div></div></div> 1 Radiator Enclosure / Grill
<div><div></div><div></div></div>	<div><div></div><div></div></div>	
Rear Frame	Sheet Metal Panels	Steps / Ladder
<div><div></div><div></div><div></div></div> <div>Clean for thorough inspection</div>	<div><div></div><div></div><div></div></div>	<div><div></div><div></div></div> <div>Weled to counterweight</div>
Cleaning Required	S.O.S. Taken	Service Required?
YES	YES	YES
	Engine	No date
Notes - GENERAL APPEARANCE		
Right front and left rear final drives removed, missing tow pin		

SAFETY ITEMS

Alternate Exit	Implement Safety Lockout	Rear View Mirrors
<div><div></div><div></div><div></div></div>	<div><div></div><div></div><div></div></div>	<div><div></div><div></div><div></div></div>

ROPS



One bolt missing on the ls

Seat-Belt



Due for replacement dates on belts
2/22 and 6/20

Warning / Safety Labels



OPERATOR STATION

Cab Floor



Needs cleaning

Cab Interior Trim



Needs cleaning

Consoles



Doors / Latches



Floor Boards



Glass & Windows



Seat / Suspension / Arm Rests



Switches



ECM Downloaded

NO

Radio

NO

Notes - OPERATOR STATION 1

Components removed/dead
batteries

ENGINE

Air Cleaners



Engine Air Inlet



Physical appearance, functional was
not checked

Engine Block / Cylinder Head



Engine Front / Rear Housings



Oil traces on flywheel housing

Engine Pre-Cleaner



Engine Supports



Exhaust / Muffler



Fuel Lines & Filters



Turbocharger



Physical appearance, functional was
not checked

Engine Oil Leaks
YES
Rear of oil pan, looks more like
hyd oil. Clean area and verify



Fluid Levels OK?
YES

Fuel Leaks
NO

Notes - ENGINE
Eng S/N 8NZ00245

COOLING SYSTEM

Coolers
●●●
Physical appearance, functional was
not checked

Engine Cooling Tubes & Hoses
●●●

Fan Drive
●●●

Radiator
●●●
Physical appearance, functional was
not checked

Radiator Shroud / Fan Guard
●●●

Water Pump
●●●
Physical appearance, functional was
not checked

Cooling System Leaks
NO

Notes - COOLING SYSTEM
Machine down due repairs

ELECTRICAL, STARTING AND CHARGING SYSTEM

Wiring
●●●
Physical appearance, functional was
not checked

TRANSMISSION

Case-Transfer
●●
Clean oil traces

Case-Transmission
●●
Clean oil traces

Cooler
●●
Leaks on cooler block

Transmission Oil Lines & Tubes
●●
Clean oil traces

Transmission Oil Leaks

YES

TXM filter housing wet, clean area

Notes - TRANSMISSION

Clean areas

STEERING

Articulation Hitch Pins & Bushings



Physical appearance, functional was not checked

Articulation Lock Linkage



Articulation Stops



Steering Cylinder



Physical appearance, functional was not checked

Steering Cylinder Pins & Bushings



Physical appearance, functional was not checked

Steering Oil Lines & Tubes



BRAKE

Pedal



HYDRAULICS

Lift Cylinders



Both lift cylinders leaking



Pumps & Valves



Traces of oil on pump drive area, clean and locate source

Tank Hydraulic



Clean area and check for leaks

BUCKET

Bucket Bottom



Could not lift bucket to check

Bucket Floor



Bucket Pins & Bushings



Bucket Sides



Cutting Edges



Loader Frame



Physical condition

Loader Pins & Bushings
●●●
Physical condition

Segments
●●

Teeth / Adapters
●●

Tilt Linkages
●●●

Tilt Linkages Pins & Bushings
●●●

High Lift
YES

Bucket S/N - BUCKET
500573/96-30/N30

ATTACHMENTS / WORK TOOLS

Lift Boom
YES

FINAL DRIVES

Differential / Axle Mounts
●●●

Drive Shafts
●●●

Front Axle
●●●
Needs cleaning

Front Final Drives
●
Right front final removed

📷2 Oscillation
●●●
Physical condition not functional

Rear Axle
●●
Clean oil traces off

📷1

Rear Final Drives
●
Left rear final removed

📷2 Trunion
●●●
Physical condition with not functional

TIRES

	Make / Serial#	Tread Depth in 1/32"	% Life Remaining	Recapped	Tread Cuts/Chunks	Side Cuts Section
Left Front	Firestone Load- Dozer			NO	YES	YES
Left Rear	Firestone Load- Dozer	111	72	NO	YES	YES

Right Front	Firestone Load-Dozer			NO	YES	YES
Right Rear	Firestone Load-Dozer	60	39	NO	YES	YES

Rims / Wheels Condition



Tire Size - TIRES
53.5/85-57

COMMENTS, MISC. REPAIRS, GENERAL REMARKS

comment 1
See equipment history for repairs done, all in Spanish

Date of Machine Inspection
Inspected on 8/7/25 at 43050 hours (hours provided by client)
dead batteries

MARKETING PHOTOS (29)









