

2012 CAT 994H WHEEL LOADER

INSPECTION DETAILS

Inspection Type	Consignment
Inspection Form	Wheel Loaders
Inspection #	10220941
Inspection Status	Inspected
Created	08/05/25 09:19:15
Updated	08/08/25 22:21:05
Created By	Akutey, Solomon
Inspector	Akutey, Solomon
Reviewers	Akutey, Solomon
Serial #	DWC00300
SMU / Hours	33,249
Location	Mexico



FEATURES

General

- Air Conditioner
- Boom, GP
- Coupler Type - Mechanical
- Lift - Standard
- ROPS - Enclosed
- Auto Shift
- Counterweight
- Engine Enclosures
- Lighting
- Steering Type - Joystick
- Beacon
- Coupler - Standard
- Fire Extinguisher
- Mirrors

Regulatory

- Ultra Low Sulfur Diesel Fuel

Technology

- Vital Information Management System (VIMS)

Attachments

- Bucket

CONDITION

Good



Fair



Poor

Approved Repair

GENERAL APPEARANCE**PARTS & LABOR TOTAL: 1400.00**

Battery Compartment



Bottom Guards



Bumper



Cab / Canopy



Counterweight



Engine Enclosure Panels



Fenders



Front Frame



Fuel Tank



Grab Handles / Handrails



Hood Panels



Hinges on top platform is been welded

Paint & Decals



Weathered/faded

Platforms



Not in place due to TXM removal

Radiator Enclosure / Grill



Rear Frame



Sheet Metal Panels



Steps / Ladder



Both welded to counterweight



Cleaning Required

YES

Labor: 1400.00

S.O.S. Taken

YES

Engine

Service Required?

YES

No date

Notes - GENERAL APPEARANCE

Transmission was out at the time of inspection.

SAFETY ITEMS**PARTS & LABOR TOTAL: 960.00**

Alternate Exit



Implement Safety Lockout



Rear View Mirrors



ROPS



Seat-Belt



Warning / Safety Labels



Date on belt 6/19 and companion belt 4/18

Parts: 600.00

Labor: 360.00

ROPS Certification Label



YES

OPERATOR STATION

Cab Floor



Cab Interior Trim



Needs cleaning

Consoles



Dash Console



Doors / Latches



Floor Boards



Gauges / Instrument Panel



Glass & Windows



Hour Meter



Interior Lights



Switches



ECM Downloaded

YES

ENGINE

Air Cleaners



Engine Air Inlet



Engine Block / Cylinder Head



Engine Exhaust



Engine Front / Rear Housings



Engine Pre-Cleaner



Engine Supports



Exhaust / Muffler



Fuel Lines & Filters



Engine Oil Leaks

YES

Oil filter housing has minor leaks

Fluid Levels OK?

YES


Fuel Leaks


NO

Water In Engine Oil?
NO

Notes - ENGINE
Did not run engine, TXM was out for repairs

COOLING SYSTEM


Coolers

Lock on cooler leaking

Engine Cooling Tubes & Hoses


Fan


Fan Drive


Radiator


Radiator Shroud / Fan Guard


ELECTRICAL, STARTING AND CHARGING SYSTEM


Battery & Wiring



Beacon



TRANSMISSION


Notes - TRANSMISSION
No transmission in machine, it been removed for repairs


STEERING

Articulation Hitch Pins & Bushings


Articulation Lock Linkage


Articulation Stops


Steering Cylinder Pins & Bushings

Left cylinder starting to leak

 1

BRAKE

Pedal


HYDRAULICS

Lift Cylinders ●●●	Pumps & Valves ●●● Pump/drive leaking	Tank Hydraulic ●●●
Tilt Cylinders ●●●		

BUCKET

Bucket Bottom ●●●	Bucket Floor ●●●	Bucket Pins & Bushings ●●● Could not check for play
Bucket Sides ●●●	Loader Frame ●●●	Loader Pins & Bushings ●●●
Segments ●●● Could not lift bucket to check, machine down	Teeth / Adapters ●●●	📷1 Tilt Linkages ●●●
Tilt Linkages Pins & Bushings ●●●		
High Lift YES		
Bucket S/N - BUCKET ANX00139	Bucket Size 15 M3	Notes - BUCKET Pump, drive shaft in the bucket 📷6

ATTACHMENTS / WORK TOOLS

Lift Boom YES		
------------------	--	--

FINAL DRIVES

Differential / Axle Mounts ●●●	Differentials ●●●	Drive Shafts ●●● Out of machine in bucket
-----------------------------------	----------------------	---

Front Axle
●●●

Front Final Drives
●●●

Oscillation
●●●
Could not operate machine, visual

Rear Axle
●●●

Rear Final Drives
●●●

Trunion
●●●
Could not operate machine, visual


Axles, Differentials, Finals-Leaks
NO

TIRES

	Make / Serial#	Tread Depth in 1/32"	% Life Remaining	Recapped	Tread Cuts/Chunks	Side Cuts Section
Left Front	Michelin XMine D2			NO	YES	YES
Left Rear	Michelin XMine D2			NO	YES	YES
Right Front	Michelin XMine D2			NO	YES	YES
Right Rear	Michelin XMine D2			NO	YES	YES

Rims / Wheels Condition
●●

Notes - TIRES
Both front tires have chains, left rear one lug nut missing, sections on rim lock been torched out

7 Tire Size - TIRES
55/80R57

COMMENTS, MISC. REPAIRS, GENERAL REMARKS

comment 1

Transmission was out of machine, side and top panels removed.

comment 2

See equipment history, lot of repairs done but in Spanish.

Date of Machine Inspection

Inspected on 8/7/25 at 33249 hours

MARKETING PHOTOS (23)









LINE ITEM PHOTOS (18)

Steps / Ladder

●●

Both welded to counterweight



ROPS Certification Label

YES



Steering Cylinder Pins & Bushings

●●

Left cylinder starting to leak



Teeth / Adapters



Notes - BUCKET

Pump, drive shaft in the bucket





Notes - TIRES

Both front tires have chains, left rear one lug nut missing, sections on rim lock been torched out



