

2007 KENWORTH T800 DUMP TRUCKS

INSPECTION DETAILS

Inspection Type	Consignment
Inspection Form	Standard
Inspection #	10224003
Inspection Status	Inspected
Created	08/18/25 10:58:14
Updated	08/19/25 11:10:30
Created By	Earl, Ryan
Inspector	Earl, Ryan
Transmission Serial #	6610223344
Engine Serial #	LEE01323
Serial #	1NKDLU9X58J214003
Location	TUCSON, AZ, United States



FEATURES

General

- **148,772 MILES**
- **17 FT STEEL DUMP BED**
- **6 SPEED ALLISON TRANSMISSION**
- **Beacon**
- **Bed Liner - Steel**
- **BLACK FRAME**
- **CAB EXTERIOR : YELLOW**
- **CATERPILLAR C13 380 HP ENGINE**
- **ELECTRIC DUMP COVER**
- **GAWR INTERMEDIATE : 20,000 LB**
- **GAWR-FRONT : 14,600 LB**
- **GAWR-REAR : 20,000 LB**
- **GVWR : 54,600 LB**
- **Lighting**
- **Radio - Bluetooth**
- **SCALE WEIGHT : 17,250 LB**
- **THIS ENGINE COMPLIES WITH U.S. EPA AND CALIFORNIA REGULATIONS**

NOTES

INSPECTION FOR CONSIGNMENT.

CONDITION

●●● Good

●● Fair

● Poor

Approved Repair

GENERAL CONDITION

Body

●●●

COMPLETE WITH HOOD REPAIRS
NEEDED.

ENGINE HOOD

●●

HOOD LATCH BROKE LF SIDE, PAINT
AND CLEAR COAT PEELING, HOOD
INSULATION LOOSE, AND HOOD
CRACKED AND DOES NOT SIT SQUARE.

● 7

Frame

●●●

General

●●●

Machine Starts and is Operable
YES

BATTERIES NEEDED, HAD TO
JUMP.

S.O.S. (All Compartments)

YES

ENG TRANS

Tires are Aired Up and Drivable

YES

Visible Oil Leaks
YES

SAFETY ITEMS

Back Up Alarm

●

BACK UP ALARM INOPERABLE.

BRAKE AIR TANKS

●●

OIL FROM BOTH TANKS.

● 1

Horn

●●●

Seat Belt / Date
●●
TAG FRAYED.

Parking Brake Functioning
YES

Safety Decals Legible
YES

Service Brakes Functioning
YES

OPERATOR STATION

Air Conditioner

●

AC COMPRESSOR CLUTCH DOES NOT
ACTIVATE, NO COLD AC.

Armrests

●●●

Cab Filter / Heat Vent Louvres

●●●

Dash Console 	2	Door Latches / Hinges / Seals 	Floor Boards / Mats
PTO PANEL LOOSE AND MISSING BOLTS. 		DOOR WEATHER STRIPPING IN CAB TORN.	
Gauges 	2	Headliner 	Heater / Defroster
Hour Meter 	1	Hydraulic Controls 	1 Interior Lights
Interior Plastic / Fabric 		Mirrors 	2 Monitoring Display
Pans/Guards 		Radio 	Seat Cushions / Suspension / Type
Switches 	1	Transmission Controls 	1 Visor / Sunshade
DUMP BED SWITCH DOES NOT ILLUMINATE.			
Windows 	2	Windshield Wipers 	2
DRIVER SIDE AND REAR WINDOW CRACKED.			
Current O&MM NO NEEDS BOOKS.	1	Current Safety Manual NO	

ENGINE

Belts / Pulleys 	Engine Oil Level / Condition 	Engine Supports / Mounts
DRY ROTTED.	ENGINE OIL OVERFILLED.	
Exhaust / Muffler / Stack 	Fuel Injection System 	Governor

Intake / Air Filters

 DUSTY.

Operating Condition

 COMPRESSOR RELIEF VALVE ACTIVATING TO FREQUENTLY, NEEDS TROUBLESHOT.

Turbocharger / Blower**Apparent Other Engine Damage**

NO

Blow By

NO

Emissions Decal Legible

 **YES**

Fuel Leaks

NO

Oil Leaks

 **YES**

Service Needed

YES

LEAK ON RIGHT SIDE OF ENGINE, APPEARS TO BE FROM ENGINE OIL PAN.

Water in Oil

NO

Arrangement Number

305-9788

Engine S/N

LEE01323

 **1****Oil Pressure (H/L/N)**

NORMAL

Smoke Color (B/D/L/W)

NORMAL

COOLING SYSTEM**Anti-Freeze Level / Color / Condition**

 **BELOW FILL LINE.**

Belts / Pulleys - COOLING SYSTEM

 **DRY ROTTED.**

Fan **1****Fan Shrouds / Guards****Hoses / Tubes**

 **COOLANT LEAK AT UPPER HOSE / THERMOSTAT HOUSING.**

Radiator**Water Pump****Coolant Leaks**

YES

Standard Radiator

 **YES**

 **1**

ELECTRICAL, STARTING AND CHARGING SYSTEM

Batteries / Cables / Master
Disconnect

●
BATTERIES NEEDED, HAD TO JUMP.

Beacon / Strobe


Starter / Type


Wiring



'TOP LIGHT FUSE IN BATTERY BOX
AND PTO FUSES BEHIND IGNITION
SWITCH', WRITTEN IN CAB ON LEFT
SIDE BELOW STEERING CONSOLE,
WIRING NEEDS INSPECTED FOR
QUALITY CONTROL.



Work Lights



CAB MARKER LIGHTS OUT.



COMMENTS, MISC. REPAIRS, GENERAL REMARKS

comment 1
FRONT HUB CAPS SEEPING.



comment 2
TRANSMISSION LEAKS.



comment 3
HYDRAULIC LEAKS - FILTER AND
LINES FROM SUPPLY SIDE OF
FILTER.



comment 4
DUMP BODY DENTS AND LEFT
DUMP LADDER BENT.



comment 5
DUMP LINER RUSTED.



comment 6
TIRES - 315/80R22.5 - MIX
BETWEEN IRONMAN I-301 /
DYNATRAC DL380 / AMERICUS
OS3000 / HERCULES AP2000 -
ALL IN FAIR TO GOOD
CONDITION.



MARKETING PHOTOS (26)









