

2022 CAT 259D3 COMPACT TRACK LOADER

INSPECTION DETAILS

Inspection Type	Trade
Inspection Form	Standard
Inspection #	10256168
Inspection Status	Completed
Created	12/08/25 14:57:06
Updated	12/11/25 09:32:09
Created By	Preskitt, Billy
Inspector	Preskitt, Billy
Reviewers	Preskitt, Billy
Salesperson	Schultis, Derrick R.
Stock #	E196732
Serial #	CW920348
SMU / Hours	1,184
Location	Eloy, AZ 85131, United States



FEATURES

General

- 2 Speed Travel
- Air Conditioner
- Auxiliary Hydraulics Flow - Standard Flow
- Coupler Type - Hydraulic
- Heater / Defroster
- Lighting
- Product Link
PRODUCT LINK, CELLULAR PL243
- Radio - AM FM Radio
- ROPS - Enclosed
- Self Leveling

Regulatory

- Emissions Level - EPA - Tier4
- Emissions Level - Japan - 2014 Regulation
- Emissions Level - Korea - Korea-Tier4
- Ultra Low Sulfur Diesel Fuel

Attachments

- Bucket
80"

CONDITION

●●● Good

●● Fair

● Poor

Approved Repair

GENERAL CONDITIONBody
●●●Frame
●●●General
●●●ET Product Status Report
Download
YESLogged / Active Codes
NOMachine Starts and is Operable
YESS.O.S. (All Compartments)
NO
Engine and hydraulicVisible Oil Leaks
NO**GENERAL APPEARANCE**Cab or Canopy
●●●Counterweight
●●●Crankcase Guard / Battery Box
●●●Decals
●●●
Decals are scratched and peelingEng. Enclose Hood / Stack
●●●
Engine compartment door is bent (opens and closes as it should)Fuel Tank
●●●Grab Irons
●●●Main Frame Welds
●●●Paint
●●●
Has scratchesRadiator Grill & Shroud
●●●
strut is leaking, screen has small dentSheet Metal
●●●Steps / Ladder
●●●Cleaning Required
YES**SAFETY ITEMS**Back Up Alarm
●●●Camera(s)
●●●Dead Engine Lowering Valve
●●●

Horn
●●●

ROPS
●●●

Safety Locks / Pins
●●

●1

Lift arm safety lock is broken

Seat Belt / Date  1
●
seat belt is expired 07-2022

Parking Brake Functioning
YES

ROPS Certification Plate
YES

 1 Safety Decals In Place
YES

Safety Decals Legible
YES

OPERATOR STATION

Air Conditioner
●●●
vent temp 53.4

 1 Armrests
●●●

Cab Filter / Heat Vent Louvres
●●●

●1

Dash Console
●●●
right side console is missing plug

 1 Door Latches / Hinges / Seals  3
●●●

Door seal is torn. Missing top safety latch. inside door latch cover is cracked (replace only the emergency release latch on front window)

Floor Boards / Mats
●●●

Gauges
●●●

Headliner
●●●

Heater / Defroster
●●●
vent temp 109.6

●1

Hour Meter - GAUGES,
OPERATION STATION, CONSOLE
●●●

Hydraulic Controls
●●●

 2 Interior Lights
●●●

●1

Interior Plastic / Fabric
●●●

Mirrors
●●●
Missing mirror

Monitoring Display
●●●

Radio
●●●

 1 Seat Cushions / Suspension /
Type
●●●

 1 Switches
●●●

Visor / Sunshade

Windows

Windshield Wipers

Wiper blade is torn



Current O&MM
YES

1 Current Safety Manual
YES



ENGINE

Belts / Pulleys - ENGINE

2 Engine Oil Level / Condition

Exhaust / Muffler / Stack

Fuel Injection System

Intake / Air Filters

Part of service

1 Operating Condition - ENGINE

Turbocharger / Blower

Apparent Other Engine Damage
NO

Blow By
NO

Emissions Decal Legible
YES



Fuel Leaks
NO

Knocking
NO

Oil Leaks
NO

Pre Lube System
NO

Water in Oil
NO

EMISSIONS

Aftertreatment System Codes
NO

Leaks / Type
NO



COOLING SYSTEM

Anti-Freeze Level / Color /
Condition

Red

1 Coolers

Fan

Fan Drive / Type

Fan Shrouds / Guards

Hoses / Tubes



Radiator



Water Pump



Compression in Radiator

NO

Coolant Leaks

NO

Oil in Anti-Freeze

NO

Standard Radiator

YES

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator



Batteries / Cables / Master

Disconnect



Lighting



Right rear tail light is not working

Starter



Wiring



TANDEMS/GEARINGS/BEARINGS/CHAINS

Front Torsion Bars



Housings, Left



Housings, Right



Operating Condition



Planetarys / Differential, Left



Planetarys / Differential, Right



Rear Torsion Bars



Travel Controls



Travel Motors



Travel Pumps



Magnetic Plugs Removed &
Checked?

NO

HYDRAULICS

Detent Switch



Hoses / Lines



Lift Cylinders



auxiliary ports are missing dust caps

Overall Operating Condition -
HYDRAULICS



Pump & Valves



Tank



2

hydraulic tank strainer is leaking

Tilt Cylinder



Leaks - HYDRAULICS

YES

Quoted under tank

ATTACHMENTS / WORK TOOLS

Angle Broom

NO

Auger

NO

Cold Planer

NO

Fork Line

NO

Hammer

NO

Landscape Tiller

NO

Mulcher Head

NO

Pick-up Broom

NO

Stump Grinder

NO

Trencher

NO

Wheel Saw

NO

BUCKET

Bucket Bottom



Has dents

2

Bucket Linkage



Bucket Sides



2

Cutting Edges



1

Loader Frame



Loader Pins & Bushings



Quick Coupler



Bucket step

YES

step is bent on bucket (can be straightened weld repair)

1

Notes - BUCKET

both Bucket mounts are bent
(can be straightened weld
repair)

UNDERCARRIAGE

Idlers



Roller



Roller Frame



Sprocket



Track / Belt Condition



5

both Tracks have cuts

COMMENTS, MISC. REPAIRS, GENERAL REMARKS

comment 1


Service

comment 2

Inspection


MARKETING PHOTOS (30)











LINE ITEM PHOTOS (51)

Decals



Decals are scratched and peeling



Eng. Enclose Hood / Stack



Engine compartment door is bent (opens and closes as it should)



Radiator Grill & Shroud



strut is leaking. screen has small dent



Camera(s)



Safety Locks / Pins



Lift arm safety lock is broken



Seat Belt / Date




seat belt is expired 07-2022



ROPS Certification Plate

YES



Air Conditioner



vent temp 53.4



Cab Filter / Heat Vent Louvres



Dash Console



right side console is missing
plug



Door Latches / Hinges / Seals



Door seal is torn. Missing top safety latch. inside door latch cover is cracked (replace only the emergency release latch on front window)



Heater / Defroster



vent temp 109.6



Hydraulic Controls



Interior Lights



Mirrors

Missing mirror



Radio

3/3



Seat Cushions / Suspension /

Type

3/3



Windshield Wipers




Wiper blade is torn




Current O&MM

YES



Current Safety Manual

YES



Belts / Pulleys - ENGINE



Intake / Air Filters



Part of service



Emissions Decal Legible

YES



Anti-Freeze Level / Color /

Condition



Red



Lighting



Right rear tail light is not working



Hoses / Lines



auxiliary ports are missing dust caps



Tank



hydraulic tank strainer is leaking



Bucket Bottom



Has dents



Bucket Sides



Cutting Edges



Bucket step

YES

step is bent on bucket (can be straightened weld repair)



Track / Belt Condition



both Tracks have cuts

