



2024 KUBOTA CORPORATION
SSV75
SKID STEER LOADERS

INSPECTION DETAILS

Inspection Type	Marketing
Inspection Form	Skid Steers
Inspection #	10258609
Inspection Status	Created
Created	12/17/25 11:15:04
Updated	12/23/25 11:24:23
Created By	Fuller, Scott U.
Inspector	Fuller, Scott U.
Reviewers	Fuller, Scott U.
Salesperson	Heath, Jason
Stock #	E212403
Serial #	KBCZ141CARGG41675
SMU / Hours	600
Location	Henderson, NV, United States



FEATURES

General

- 2 Speed Travel
- Air Conditioner
- Auxiliary Hydraulics Flow - High Flow
- Coupler Type - Hydraulic
- Heater / Defroster
- Lighting
- Radio - AM FM Radio
- ROPS - Enclosed

Regulatory

- Emissions Level
T4
- Ultra Low Sulfur Diesel Fuel

Technology

- Pilot Control

CONDITION

<div><div></div><div></div><div></div></div> Good	<div><div></div><div></div></div> Fair	<div><div></div></div> Poor
---	--	-----------------------------

GENERAL APPEARANCE

Body Frame		Cab or Canopy		Counterweight		
<div><div></div><div></div><div></div></div>		<div><div></div><div></div><div></div></div>		<div><div></div><div></div><div></div></div>		
Engine Access Door	<div><div></div><div></div></div>	<div><div></div><div></div><div></div></div> 3	Fuel Tank	<div><div></div><div></div><div></div></div>	Grab Irons	<div><div></div><div></div><div></div></div>
Dent in lower left corner of engine door and at top of engine door.		Residue on tank. Assume from overfilling.				
Guarding Panels	<div><div></div><div></div><div></div></div>	Paint & Decals	<div><div></div><div></div><div></div></div>	Plastic	<div><div></div><div></div><div></div></div>	
		Some minor scratches				
Radiator Grill & Shroud	<div><div></div><div></div><div></div></div>	Sheet Metal	<div><div></div><div></div></div>	<div><div></div><div></div><div></div></div> 1	Steps / Ladder	<div><div></div><div></div><div></div></div>
		Quick disconnect manifold guard is bent.				
Cleaning Required		S.O.S. Taken		Service Required?		
YES		YES		YES		
Wash and detail				Most recent service is unknown.		

SAFETY ITEMS


Alternate Exit	Back-Up Alarm	Horn
●●●	●●●	●●●
Lift Arm Safety Brace	Parking Brake	Rear View Mirrors
●●●	●●●	●●●
Reflectors / Reflective Labels	Seat-Belt	1
●●●	●●●	Warning / Safety Labels
	Manufactured in 2023	One torn label in cab
ROPS	ROPS Certification Label	
YES	YES	

OPERATOR STATION







<div>Air Conditioner</div> <div><div><div></div><div></div><div></div></div></div> <div>Cooled to 46 degrees at 65 ambient temp</div>	<div>1</div>	<div>Cab Interior Trim</div> <div><div><div></div><div></div><div></div></div></div>	<div>Controls-Throttle</div> <div><div><div></div><div></div><div></div></div></div>
		<div>Doors / Latches</div> <div><div><div></div><div></div><div></div></div></div>	<div>EMS Panel / Warnings</div> <div><div><div></div><div></div><div></div></div></div>
		<div>Gauges</div> <div><div><div></div><div></div><div></div></div></div>	<div>Glass & Windows</div> <div><div><div></div><div></div><div></div></div></div>
		<div>HVAC System</div> <div><div><div></div><div></div><div></div></div></div>	<div>Joystick Console</div> <div><div><div></div><div></div><div></div></div></div>
		<div>Seat / Suspension / Arm Rests</div> <div><div><div></div><div></div><div></div></div></div>	<div>Switches</div> <div><div><div></div><div></div><div></div></div></div>
<div>Windshield Wipers</div> <div><div><div></div><div></div><div></div></div></div>			
<div>Cameras</div> <div>YES</div> <div>Non-OEM camera installed. Wiring is broken and camera is inop.</div>	<div>2</div>	<div>Current O&MM</div> <div>NO</div>	<div>Current Parts Manual</div> <div>NO</div>
		<div>ECM Downloaded</div> <div>NO</div>	<div>Radio</div> <div>YES</div>
<div>Current Safety Manual</div> <div>NO</div>			

ENGINE








<div>Air Cleaners</div> <div><div><div></div><div></div><div></div></div></div>	<div>Belts & Pulleys</div> <div><div><div></div><div></div><div></div></div></div>	<div>Engine Block / Cylinder Head</div> <div><div><div></div><div></div><div></div></div></div>
<div>Engine Operating Condition</div> <div><div><div></div><div></div><div></div></div></div>	<div>Engine Supports</div> <div><div><div></div><div></div><div></div></div></div>	<div>Exhaust / Muffler</div> <div><div><div></div><div></div><div></div></div></div>
<div>Fuel Lines & Filters</div> <div><div><div></div><div></div><div></div></div></div>	<div>Governor</div> <div><div><div></div><div></div><div></div></div></div>	<div>Turbocharger / Blower</div> <div><div><div></div><div></div><div></div></div></div>

Blow By NO	Compression in Radiator NO	Emission Label YES
Engine Oil Leaks NO	Fluid Levels OK? NO Hyd oil is low.	 1Knocking NO
Water in Oil NO		
Anti-Freeze Color Green	Oil Pressure (H/L/N) Normal	Smoke (B/D/L/W) Normal




COOLING SYSTEM


Coolers 	Engine Cooling Tubes & Hoses 	Fan 
Fan Drive 	Radiator 	Water Pump 
Cooling System Leaks NO		




ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator 	Batteries / Cables 	Battery Compartment 
Lighting 	Starter 	Wiring  Broken wiring to RV camera  1
Block Heater NO	Ether Aid NO	




HYDRAULICS




Controls-Hydraulic 	Controls-Travel & Steering 	Cylinder Pins & Bushings 
--	---	---

Hydraulic Oil Lines & Tubes 2
Aux. line Quick connect manifold is broken and held in place with a large hose clamp.



Hydraulic Operating Condition



Lift Cylinders


Pumps & Valves





Tank Hydraulic





Tilt Cylinder



Travel Drive Motors





Hydraulic System Leaks 2
YES
Possible seepage at hyd tank sight gauge. Excess oil on engine compartment floor also from hyd seep or tank overfill. Needs cleaned and rechecked to verify leak source.

BUCKET

Bucket Pins & Bushings


Coupler Pins & Bushings


Loader Frame


Loader Pins & Bushings


Coupler Quick Disconnect
YES

Notes - BUCKET
No bucket

TIRES

	Make / Serial#	Tread Depth in 1/32"	% Life Remaining	Recapped	Tread Cuts/Chunks	Side Cuts Section
Left Front	Ty Cushion Smooth	0		NO	YES	NO

Left Rear	Ty Cushion Smooth	0	NO	YES	NO
Right Front	Ty Cushion Smooth	0	NO	YES	NO
Right Rear	Ty Cushion Smooth	0	NO	YES	NO

Rims / Wheels Condition



Axles, Differentials, Finals-Leaks
NO

Tire Size - TIRES
34x12-20/8.00

COMMENTS, MISC. REPAIRS, GENERAL REMARKS

comment 1
Inspected 11/3/2025 with 558
hrs.

comment 2
Trade in inspection performed
12/16/2025 with 600 hours



13

MARKETING PHOTOS (16)





