

2016 CAT

950M

WHEEL LOADER

INSPECTION DETAILS

Inspection Type	Marketing
Inspection Form	Standard
Inspection #	10212549
Inspection Status	Completed
Created	06/27/25 12:27:06
Updated	07/18/25 14:55:10
Created By	Calderas, Marco
Inspector	Calderas, Marco
Reviewers	Calderas, Marco
Salesperson	Schultis, Derrick R.
Stock #	E195079
Serial #	EMB02430
SMU / Hours	8,787
Location	Eloy, AZ, United States



FEATURES

General

- Air Conditioner
- Coupler Type - Hydraulic
- Lift - Standard
- Product Link
- ROPS - Enclosed
- Counterweight
- Differential Lock
- Lighting
- Radio - AM FM Radio
- Coupler - Quick
- Engine Enclosures
- Mirrors
- Ride Control

Regulatory

- Ultra Low Sulfur Diesel Fuel

Attachments

- Bucket
- Forks - Block

CONDITION

●●● Good

●● Fair

● Poor

Approved Repair

GENERAL CONDITIONBody
●●●Frame
●●●General
●●●ET Product Status Report
Download
YESLogged / Active Codes
NOMachine Starts and is Operable
YESS.O.S. (All Compartments)
NOTires are Aired Up and Drivable
YESVisible Oil Leaks
NO**GENERAL APPEARANCE**Cab or Canopy
●●●Counterweight
●●●
Has been repaired.Crankcase Guard / Battery Box
●●●Decals
●●●Differential Supports
●●●Eng. Enclose Hood / Stack
●●●Fenders
●●●Fiberglass
●●●Front Frame
●●●Fuel Tank
●●●Grab Irons
●●●Guards / Screens
●●●

●1

Front fenders are cracked

Right rear hand holds are cracked and bent

Belly pans are bent.

Paint
●●●Plastic
●●●Pre-Cleaner Bowl
●●●

Has been painted

Radiator Grill & Shroud
●●●Rear Frame
●●●Sheet Metal
●●●

●1

Right rear is bent upward.

Steps / Ladder

5

Left side rear is missing belts and steps. Has bent brackets. Left side cab entry belts damaged and has step welded in place

SAFETY ITEMS

Back Up Alarm



Camera(s)



1

Horn



ROPS



Seat Belt / Date



Secondary Exit



Parking Brake Functioning

YES

ROPS Certification Plate

YES

1

Safety Decals Legible

YES

Safety Locks / Pins

YES

1

Service Brakes Functioning

YES

Missing pin keepers on frame lock

OPERATOR STATION

Air Conditioner



1

Armrests



Cab Filter / Heat Vent Louvres



Ambient temp at 109.2F and vent temp at 53.4F

Dash Console



Door Latches / Hinges / Seals



Door strut is blown and seal is torn.
Door pocket is cracked.(Door does not lock shut right) almost have to slam it to get it close

3

Floor Boards / Mats



Gauges



Headliner



Heater / Defroster



Hour Meter



Hydraulic Controls



Interior Lights



2

Inoperable.

Interior Plastic / Fabric


Mirrors


Monitoring Display


Radio

Missing antenna

 1 Seat Cushions / Suspension / Type

RIPPED CUSHION

 1 Switches


Transmission Controls


Visor / Sunshade

Damaged. Will not hold

 1 Windows


Windshield Wipers

Washer pumps are inoperable

 1 Current Parts Manual
NO

Current Safety Manual
NO

Fuel Level
1/4

ENGINE

Belts / Pulleys


Engine Oil Level / Condition


Engine Supports / Mounts


Exhaust / Muffler / Stack


Governor


Intake / Air Filters


Operating Condition


Turbocharger / Blower


Blow By
NO

Fuel Leaks
NO

Knocking
NO

Oil Leaks
NO

Water in Oil
NO

Oil Pressure (H/L/N)
Normal

Smoke Color (B/D/L/W)
Normal

EMISSIONS

Aftertreatment Heat Shields / Guards	DEF Lines / Wiring	Diesel Exhaust Fluid (DEF) Tank
Diesel Particulate Filter (DPF) Condition / Service Hours		
Aftertreatment System Codes	Leaks / Type	
NO	NO	

COOLING SYSTEM

Anti-Freeze Level / Color / Condition	Belts / Pulleys - COOLING SYSTEM	Coolers
Red		
Fan	Fan Drive / Type	Fan Shrouds / Guards
Hoses / Tubes	Radiator	Water Pump
Compression in Radiator	Coolant Leaks	Standard Radiator
NO	NO	YES

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator	1	Batteries / Cables / Master Disconnect	Wiring
Work Lights			
Signal Lights			
YES			

TRANSMISSION

Case
●●●

Controls - TRANSMISSION
●●●

Cooler
●●●

Drive Shaft
●●●

Leaks - TRANSMISSION
●●●

Lines / Fittings - TRANSMISSION
●●●

Operating Condition -
TRANSMISSION
●●●

Pump - TRANSMISSION
●●●

Seals
●●●

Torque Converter -
TRANSMISSION
●●●

Transmission
●●●

Transmission - Forward Shifts
●●●

Transmission - Reverse Shifts
●●●

Universal Joints - TRANSMISSION
●●●

Transmission - Noisy
NO

STEERING

Articulate P & B
●●●

Hand Metering Unit
●●●

Lines / Fittings - STEERING
●●●

Pumps
●●●

Steering Cylinder
●●●

Steering Linkage
●●●

Has movement at pins and bushings
both cylinders rod and barrel ends

Steering Valves / Pumps
●●●

Steering Wheel Tilt / Extend
●●●

Valves
●●●

BRAKE

Accumulators
●●●

Brake Drums / Rotors
●●●

Control Valve
●●●

Hydraulic Pumps
●●●

Lines
●●●

Lines / Tubes
●●●

Parking Brake - BRAKE



Pedal



Pump - BRAKE



Type (Wet, Dry)



Holds In Park

YES

Leaks - BRAKE

NO

Holding What Gear?

3rd

HYDRAULICS

Accumulator Charge - Ride

Control



Bucket & Hoist Kickout



Control Linkage



Hose Lines



Hoses & Tubes - HYDRAULICS



Lift Cylinders



Overall Operating Condition



Pumps & Valves



Tank



Has residue under tank area at right side behind transmission.

Tilt Cylinder



Leaks - HYDRAULICS

NO

ATTACHMENTS / WORK TOOLS

Operating Condition -

ATTACHMENTS / WORK TOOLS



MISSING LOCKS



Forks

YES

MISSING FORK LOCKS AND

HARDWARE

7

BUCKET

Bucket Bottom



Bucket Floor



Bucket Linkage - BUCKET



Bucket Sides



Loader Frame



Loader Pins & Bushings



Quick Coupler



Segments



Teeth / Adapters



2

Worn

Worn

High Lift

NO

Standard Lift

YES

Bucket Capacity

Unknown

Bucket S/N - BUCKET

108"

Notes - BUCKET

Bent spill guard

3

FINAL DRIVES

Differentials



Front Axle



Front Final Drives



Oscillation



Rear Axle



Rear Final Drives



Trunion



Has movement

1

Wheel Lugs & Rims - FINAL
DRIVES



Leaks - FINAL DRIVES

NO

TIRES

Make / Serial#	Tread Depth in 1/32"	% Life Remaining	Recapped	Tread Cuts/Chunks	Side Cuts Section
----------------	-------------------------	---------------------	----------	----------------------	----------------------

Left Front	Bridgestone	12	26	NO	YES	YES
Left Rear	Road guider	34	90	NO	YES	YES
Right Front	Advance	29	58	NO	YES	YES
Right Rear	Road guider	33	88	NO	YES	YES

Spare
NO


Average Life Remaining - TIRES
65.5

Tire Size - TIRES
23.5R25

MARKETING PHOTOS (28)











LINE ITEM PHOTOS (73)

Counterweight



Has been repaired.



Fenders



Front fenders are cracked





Grab Irons



Right rear hand holds are cracked and bent





Guards / Screens



Belly pans are bent.



Paint



Has been painted



Sheet Metal



Right rear is bent upward.



Steps / Ladder



Left side rear is missing belts and steps. Has bent brackets.

Left side cab entry belts damaged and has step welded in place





Camera(s)
● ● ●



ROPS Certification Plate

YES



Safety Locks / Pins

YES

Missing pin keepers on frame lock



Air Conditioner



Ambient temp at 109.2F and
vent temp at 53.4F



Door Latches / Hinges / Seals



Door strut is blown and seal is torn. Door pocket is cracked.(Door does not lock shut right) almost have to slam it to get it close



Interior Lights



Inoperable.



Radio



Missing antenna



Seat Cushions / Suspension /

Type



RIPPED CUSHION



Visor / Sunshade



Damaged. Will not hold



Windshield Wipers



Washer pumps are inoperable



Alternator



Steering Cylinder



Has movement at pins and bushings both cylinders rod and barrel ends



Lift Cylinders



Tank



Has residue under tank area at right side behind transmission.



Tilt Cylinder



Operating Condition -
ATTACHMENTS / WORK TOOLS
●●
MISSING LOCKS




Forks

YES

MISSING FORK LOCKS AND
HARDWARE





Segments
●●●
Worn





Teeth / Adapters



Worn



Trunion



Has movement



Notes - BUCKET

Bent spill guard



Make / Serial#	Tread Depth in 1/32"	% Life Remaining	Recapped	Tread Cuts/Chunks	Side Cuts Section
Left Front	Bridgestone	12	26	NO	YES





Make / Serial#	Tread Depth in 1/32"	% Life Remaining	Recapped	Tread Cuts/Chunks	Side Cuts Section
Left Rear	Road guider	34	90	NO	YES



Make / Serial#	Tread Depth in 1/32"	% Life Remaining	Recapped	Tread Cuts/Chunks	Side Cuts Section
Right Front	Advance	29	58	NO	YES
					
					
Make / Serial#	Tread Depth in 1/32"	% Life Remaining	Recapped	Tread Cuts/Chunks	Side Cuts Section
Right Rear	Road guider	33	88	NO	YES
					

