

# 1998 CAT 375L TRACK EXCAVATORS

## INSPECTION DETAILS

Inspection Type	Consignment
Inspection Form	Excavators
Inspection #	10255552
Inspection Status	Inspected
Created	12/04/25 18:17:28
Updated	12/12/25 17:13:08
Created By	Fuller, Scott U.
Inspector	Fuller, Scott U.
Reviewers	Fuller, Scott U.
Salesperson	Pikula, William M.
Engine Serial #	TXG07489
Serial #	9WL00220
SMU / Hours	26,461
Location	NV, United States



## FEATURES

### General

- **35.5" DG tracks**
- **Hand and Foot Control**
- **Radio**
- **Air Conditioner**
- **Lighting**
- **Surestrike SS50 Hammer**
- **Engine Enclosures**
- **Mirrors**
- **Tier 3 Repowered**

## NOTES

Machine has been out of operation for more than a year per client. Batteries dead and unable to perform proper operational inspection. Expedited walk around inspection performed. See photos for condition.

**CONDITION** Good Fair Poor Approved Repair**GENERAL APPEARANCE**Bumper  
Cab  
Counterweight  


Fabricated front cab guard

Scratched and gouged.

Engine Enclosure Panels  
 3Fenders  
Fuel Tank  
Noise reduction panels damaged,  
loose .Grab Handles / Handrails  
Hood  
 1Hood Panels  


Oil residue all over top of hood.

Noise reduction panels damaged,  
loose .Main Frames  
Paint & Decals  
Radiator Enclosure / Grill  
Faded / weathered with scrapes and  
gouges throughout.Steps / Ladder  
 1Underbody Guarding Plates  


Left cat walk is bent/damaged

Cleaning Required

**YES**Machine has been out of  
operation for some time. Is very  
dirty. Inside and out.

S.O.S. Taken

**NO**

Service Required?

**YES****SAFETY ITEMS**Alternate Exit  
Reflectors / Reflective Labels  


Seat-Belt

 expiredWarning / Safety Labels  


Missing most.

**Notes - SAFETY ITEMS**

Machine down, has not been in operation for more than a year and batteries are no good. Unable to fully inspect or perform any operational checks.

**OPERATOR STATION****Cab Interior Trim**

Some cracks and breaks. Missing traction pad from right travel pedal. Missing headliner. Trim is faded and weathered.

**Dash Console****Doors / Latches****Floor Boards**

Floor mat worn.

**Glass & Windows**

Dirty/ faded. Towels stuffed on sides of front window.

**Hour Meter**

Cannot confirm actual hours. Unknown is meter is operational.

**HVAC system**

Unable to test. Multiple vent louvers are missing with towels stuffed in vents.

**Joystick Console**

Trim is faded and weathered.

**Seat / Suspension / Arm Rests**

Dirty.

**Windshield Wipers**

Washer fluid bottle is broken.

**Cameras****NO****Current O&MM****NO****Current Parts Manual****NO****Current Safety Manual****NO****Radio****YES**

## Notes - OPERATOR STATION 1

Machine down, has not been in operation for more than a year and batteries are no good. Unable to fully inspect or perform any operational checks.

---

## ENGINE

### Engine Pre-Cleaner



Precleaner bowl is broken.

### Emission Label

**YES**

### Fluid Levels OK?

**YES**

### Notes - ENGINE

Machine down, has not been in operation for more than a year and batteries are no good. Unable to fully inspect or perform any operational checks.

### Notes-Engine

Tier 3 repowered.



---

## COOLING SYSTEM

### Notes - COOLING SYSTEM

Machine down, has not been in operation for more than a year and batteries are no good. Unable to fully inspect or perform any operational checks.

---

## ELECTRICAL, STARTING AND CHARGING SYSTEM

### Batteries / Cables



Batteries are no good.

### Battery Compartment



## Notes - ELECTRICAL, STARTING

### AND CHARGING SYSTEM

Machine down, has not been in operation for more than a year and batteries are no good. Unable to fully inspect or perform any operational checks.

---

## HYDRAULICS

### Boom Lift Cylinders

1

 Right lift cylinder leaking at wiper seal.

### Hydraulic System Leaks

4

**YES**

Multiple hyd system leaks throughout.

---

## BOOM

### Boom Condition



### Boom Length (Actual Length)

27'7" Boom (per configuration)

---

## STICK

### Bucket Tilt Linkages



### Stick Conditions

1

 Crack on underside of stick near bucket end.

### Stick Length

11'2" stick (per configuration)

---

## BUCKET

### Notes - BUCKET

No bucket with machine.

## ATTACHMENTS / WORK TOOLS

Hammer

**YES**

Sure strike SS50

6

## UNDERCARRIAGE

Track Frame - Left



Excess mud build up. Could not thoroughly inspect.

1

Track Frame - Right



Excess mud build up. Could not thoroughly inspect

Notes - UNDERCARRIAGE

Machine down, has not been in operation for more than a year and batteries are no good.

Unable to fully inspect or perform any operational checks.

Track Shoes Width

35.5 inch

## COMMENTS, MISC. REPAIRS, GENERAL REMARKS

comment 1

Limited walk around inspection performed. Machine functions and operations are unknown.

43

Date of Machine Inspection

11/25/25 with 26,461 hours.

## MARKETING PHOTOS (18)





