

## WHEEL LOADER BUCKET INSPECTION

**Inspection Information** 

Inspector ID: 2654

Inspection Date: 06/19/2020
Inspection Location: Eloy, Arizona

**General Information** 

Manufacturer: Caterpillar Inventory ID: E147366
Serial Number: N/A
Part Number: 193-5840
Type/Duty/Application: Skeleton

Width (Inches): 106" Capacity (Cubic Yards): N/A

Interface: HPL Interface

Compatibility: Compatible with 926G/H & 938G/H machines with HPL coupler

Overall Condition: Good - Moderate Wear (No Major Damage)

Notes:

**Additional Information** 

Cutting Edge: Included - Bolt On

Teeth / Tips: Not Included
Side Cutters: Not Included
End Bits: Not Included
Spill Guard: Not Included
Grapple: Included

Cyliners / Lines: Included

Cylinders / Lines Condition: Poor - Need to Replace

G.E.T Overall Condition: Scrap - Excessive Wear (Damaged)

Wear Item Notes: Cylinders ok, lines need to be replaced. Needs new G.E.T.

Disclosure: Inspection, configuration, compatibility and condition should be confirmed before purchasing. All information is subject to change due to the inherit risk of inaccurate information. Call 480-633-4150 for additional details.