



**MESA, 1725 S COUNTRY CLUB DR,
ARIZONA, UNITED STATES OF
AMERICA**
1725 S Country Club Dr
Mesa, Arizona 85210-6003

Lewis, Brook L.
+1 309 264 6473
Brook.Lewis@cat.com

2016 CATERPILLAR 330FL TRACK EXCAVATORS

PRICE

\$165,000 USD

WHOLESALE

\$141,100 USD



SALES INFORMATION

Catalog #	4652190	Stock #	1166807
Serial #	MBX00549	SMU / Hours	4,014
Status	Used	Rating	Fair
Availability	Available	Location	ELOY , AZ, United States

FEATURES

- AIR CONDITIONER
- BOOM, 1 PIECE
- HAND AND FOOT CONTROL
- STRAIGHT TRAVEL PEDAL
- AM FM RADIO
- COUPLER, HYDRAULIC
- LIGHTING
- UNDERCARRIAGE, LONG
- BOOM CHECK VALVE
- ENGINE ENCLOSURES
- PRODUCT LINK

CONDITION

●●● Good

●● Fair

● Poor

GENERAL APPEARANCE●●● Bumper
Dented

●●● Car Body

●●● Counterweight

●●● Crankcase Guard / Battery Box

●●● Decals
scratched and gouged peeling

●●● Draw Bar

●●● Eng. Enclose Hood / Stack

●●● Engine Doors

●●● Fenders
Dent on right side

●●● Fuel Tank

●●● Grab Irons

●●● Hood

●●● Main Frame Welds

●●● Paint
scratched and faded

●●● Pre-Cleaner Bowl

●●● Radiator Grill & Shroud

●●● Sheet Metal

●●● Steps / Ladder

NO Cleaning Required**NO** Extra Fuel Tanks**YES** S.O.S. Taken**SAFETY ITEMS**

●●● Horn

●●● Secondary Exit

YES ROPS**YES** Safety Decals In Place**YES** Safety Decals Legible**GAUGES, OPERATOR STATION, CONSOLE**

●●● Air Conditioner

●●● Dash Console

●●● Door Latches

●●● Floor Boards

●●● Gauges

●●● Glass/Mirrors

●●● Heater

●●● Interior Lights

●●● Meter

●●● Product Link

●●● Seat Belt

●●● Seat Cushion / Arm Rest
stained and wore

●●● Switches

●●● Windshield Wipers

YES Back Up Alarm**NO** Current O&MM**NO** Current Parts Manual**NO** Current Safety Manual**YES** ROPS Certification PlateDiesel Exhaust Fluid (DEF) Level
1/2 fullFuel Level
Full**ENGINE**●● Air Cleaners
dirty part of service

●●● Belts / Pulleys

●●● Engine Supports

●●● Exhaust / Muffler

●●● Operating Condition - ENGINE

●●● Fuel Injection System

●●● Turbocharger / Blower

●●● Governor

NO Blow By

YES Fluid Levels OK?

NO Water in Oil

NO Compression in Radiator

NO Knocking

YES EPA Decal

NO Oil Leaks

Anti-Freeze Color

Red

Oil Pressure (H/L/N)

Normal

Smoke (B/D/L/W)

Normal

COOLING SYSTEM

●●● Coolers

●●● Hoses

●●● Fan

●●● Radiator

●●● Fan Drive

●●● Water Pump

NO Leaks

ELECTRICAL, STARTING AND CHARGING SYSTEM

●●● Alternator

●●● Pre-Heater

●●● Batteries / Cables

●●● Starter

●●● Lighting

●●● Wiring

YES Block Heater

Cord behind seat

HYDRAULICS

●●● Boom Cylinder

●●● Hose Lines

●●● Pumps & Valves

●●● Tank

●●● Bucket Cylinder

●●● Hydraulic Swivel

●●● Rotex

●●● Travel Motors

●●● Control Linkage

●●● Operating Condition - HYDRAULICS

●●● Stick Cylinder

Swing Drive Oil Level

Full

BOOM

●●● Boom Condition

●●● Boom Pins

●●● Pins & Bushings - BOOM

Boom Length (Actual Length)

20'2"

STICK Pins & Bushings - STICK Stick Conditions
Has some dents Stick Pins

Stick Length

12'4"

BUCKET Bucket Linkage
Movement**YES** Quick Coupler

Notes - BUCKET

No bucket

UNDERCARRIAGE

	Measurement (L)	% Worn (L)	Total Potential Hours (L)	Measurement (R)	% Worn (R)	Total Potential Hours (R)
Carrier Rollers Front	6.20	15		6.20	15	
Carrier Rollers Rear	6.22	12		6.20	15	
Idlers Front	.84	36		.84	36	
Links	4.48	16		4.50	8	
Pins & Bushings (External)	2.51	27		2.52	18	
Track Roller 1	.76	22		.74	15	
Track Roller 2	.70	5		.72	10	
Track Roller 3	guard			guard		
Track Roller 4	.74	15		.74	15	
Track Roller 5	guard			guard		
Track Roller 6	.74	15		.74	15	
Track Roller 7	guard			guard		
Track Roller 8	.70	5		.70	5	
Track Roller 9	.76	22		.76	22	
Track Shoes (Width)	1.02	20		1.02	20	

 Track Frame - Left Track Frame - Right

Link Part Number
6y-1607

Links
dry and squealing seizing up

Track Shoes
multiple track pads loose

FINAL DRIVES

 Housings

 Planetary / Diff

PHOTOS (24)







