

# 2019 CAT CB13 VIBRATORY DOUBLE DRUM ASPHALT

## INSPECTION DETAILS

Inspection Type	Marketing
Inspection Form	Standard
Inspection #	10137516
Inspection Status	Completed
Created	07/26/24 16:52:35
Updated	08/16/24 13:23:58
Created By	Calderas, Marco
Inspector	Calderas, Marco
Reviewers	Calderas, Marco
Salesperson	Schultis, Derrick R.
Serial #	PWP00376
SMU / Hours	1,590
Location	Eloy, AZ, United States



## FEATURES

### General

- Lighting
- ROPS - Open
- Water Spray System

### Emissions

- Ultra Low Sulfur Diesel Fuel

**CONDITION**

●●● Good

●● Fair

● Poor

Approved Repair

**GENERAL CONDITION**Body  
●●●Frame  
●●●General  
●●●ET Product Status Report  
Download  
**YES**Logged / Active Codes  
**NO**Machine Starts and is Operable  
**YES**S.O.S. (All Compartments)  
**NO**Visible Oil Leaks  
**NO****GENERAL APPEARANCE**Cab or Canopy  
●●●Crankcase Guard / Battery Box  
●●●Eng. Enclose Hood / Stack  
●●  
Bent on right side hydraulic compartmentFront Frame  
●●●Fuel Tank  
●●●Grab Irons  
●●●Paint  
●●  
Has minor scratches●1 Plastic  
●●●Radiator Grill & Shroud  
●●●Rear Frame  
●●●Sheet Metal  
●●●Steps / Ladder  
●●  
Has asphalt stuck to stepsCleaning Required  
**NO****SAFETY ITEMS**Horn  
●●●ROPS  
●●●Seat Belt / Date  
●●●

Back Up Alarm  
**YES**

Parking Brake Functioning  
**YES**

ROPS Certification Plate  
**YES**

Safety Decals In Place  
**YES**

Safety Decals Legible  
**YES**

Safety Locks / Pins  
**YES**

Service Brakes Functioning  
**YES**

## OPERATOR STATION

Armrests

Dash Console

Floor Boards / Mats

Gauges

Hour Meter - GAUGES,  
OPERATION STATION, CONSOLE

Hydraulic Controls

Monitoring Display

Pans/Guards

Seat Cushions / Suspension /  
Type

Seat Horizontal Track

Switches

Transmission Controls

Current O&MM  
**NO**

Current Parts Manual  
**NO**

Current Safety Manual  
**NO**

## ENGINE

Belts / Pulleys

Engine Oil Level / Condition

Engine Supports / Mounts

Exhaust / Muffler / Stack

Fuel Injection System

Governor

Intake / Air Filters  
  
Dirty

1 Operating Condition

Turbocharger / Blower

Blow By  
**NO**

Fuel Leaks  
**NO**

Knocking  
**NO**

Oil Leaks

**NO**

Service Needed

**YES**

Water in Oil

**NO**

Oil Pressure (H/L/N)

Normal

Smoke Color (B/D/L/W)

Normal

## EMISSIONS

Aftertreatment Heat Shields /  
Guards



DEF Lines / Wiring



Diesel Exhaust Fluid (DEF) Tank



Diesel Particulate Filter (DPF)  
Condition / Service Hours



Aftertreatment System Codes

**NO**

Leaks / Type

**NO**

## COOLING SYSTEM

Anti-Freeze Level / Color /  
Condition



Coolers



Fan



Fan Drive / Type



Fan Shrouds / Guards



Hoses / Tubes



Radiator



Water Pump



Compression in Radiator

**NO**

Coolant Leaks

**NO**

Oil in Anti-Freeze

**NO**

Standard Radiator

**YES**

## ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator



Batteries / Cables / Master

Disconnect



Starter / Type



Wiring



Work Lights



Jump Start Terminal

**YES**

Signal Lights

**NO**

## STEERING

Articulate P & B



Pivot P & B Trunnions



Steering Cylinder



Steering Linkage



Steering Valves / Pumps



## HYDRAULICS

Cylinders



Hose Lines



Propel Motor



Propel Pump



Tank



Vibratory Motor



Vibratory Pump



## DRUM

Drum Drive Planetaries



Drum Hubs



Drum Scrapers



Drum Surface



Isolators



Vibratory System



Water Dist. Mats




## MARKETING PHOTOS (31)













\*CAT0CB13KPWP00376\*

## LINE ITEM PHOTOS (4)

### Eng. Enclose Hood / Stack




Bent on right side hydraulic compartment



### Paint



Has minor scratches



### Steps / Ladder



Has asphalt stuck to steps



---

## Intake / Air Filters



Dirty



7/25/2024 8:24