

2006 CHEVROLET C4500 ON HIGHWAY TRUCKS

INSPECTION DETAILS

Inspection Type	Consignment
Inspection Form	Standard
Inspection #	10183504
Inspection Status	Created
Created	02/20/25 11:49:41
Updated	02/20/25 13:21:34
Created By	Fuentes, David A.
Inspector	Fuentes, David A.
Salesperson	Schultis, Derrick R.
Serial #	1GBEC1206F434778
SMU / Hours	14,652
Location	AZ, United States



FEATURES

General

- Air Conditioner
- Lighting
- Radio
- Starter, Electric

CONDITION

●●● Good

●● Fair

● Poor

GENERAL APPEARANCE

Battery Box



Bumper



●2

Car Body



Front bumper is bent (Functional)

Differential Supports



Eng. Enclose Hood / Stack



●2

Fuel Tank



Hood has stress cracks (Functional)
Left headlight bezel is broken taped
together

Grab Irons



Main Frame Welds



Paint



Plastic



Radiator Grill & Shroud



Sheet Metal



Steps / Ladder



Cleaning Required

NO

S.O.S. Taken

YES

Engine and transmission

SAFETY ITEMS

Horn



Parking Brake - SAFETY ITEMS



Reflectors



Inspection Sticker Dated

YES

●1

Safety Decals In Place

YES

Safety Decals Legible

YES

OPERATOR STATION

Air Conditioner



Vent temperature 50° ambient
temperature 78°



Dash Console



Door Latches



Doors



Floor Boards



Gauges



Glass/Mirrors



Heater



Vent temperature 110° ambient
temperature 76°



Interior Lights



Interior light not working

Odometer



146521

Seat Cushion / Arm Rest



Driver bottom seat cushion is ripped



Switches



Windshield Wipers



Current O&MM

NO

No OMM

ENGINE

Air Cleaner



Belts / Pulleys



Engine Supports



Exhaust / Muffler



Fuel Injection System



Governor



Overall Operating Condition -

ENGINE



Turbocharger / Blower



Blow By

NO

Compression in Radiator

NO

Emissions Decal

YES



Fluid Levels OK?

YES

Has Engine been rebuilt?

NO

Knocking

NO

Oil Leaks
NO

Water in Oil
NO

Anti-Freeze Color
Red

 1 Oil Pressure (H/L/N)
Normal

Smoke (B/D/L/W)
Normal

COOLING SYSTEM

Coolers


Fan


Hoses


Radiator


Water Pump


Leaks - COOLING SYSTEM
NO

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator


Batteries / Cables


Clearance Lights


LIGHTS


License plate light not working

 1 Pre-Heater


Starter


Wiring


Signal Lights
YES

Warning Lights
YES

TRANSMISSION

Case


Controls



Cooler


Drive Shaft


Lines / Fittings


Overall Operating Condition -
TRANSMISSION


Seals


Torque Converter


Transmission - Forward Shifts


Transmission - Reverse Shifts


Universal Joints


Leaks - TRANSMISSION
NO

Transmission - Noisy
NO


Transmission Type
Automatic

STEERING

Front Axle


Steering Gear Box


Steering Linkage



Torsion Rods - STEERING


BRAKE

Brake Drums / Rotors


Brake Linkage


Lines


Master Cylinder


Parking Brake - BRAKE


Pump - BRAKE


Type (Pedal, Lever)

Pedal

Type (Wet, Dry)

Dry

TRAILER BRAKES
YES



1

Holding What Gear?
All

TRUCK BODY

Bottom



Tool Box



FINAL DRIVES

Differential



Rear Axle



Springs



Wheel Lugs & Rims



TIRES

	Make / Serial#	Tread Depth in 1/32"	% Life Remaining	Recapped	Tread Cuts/Chunks	Side Cuts Section
Left Front	Track master	15		NO	YES	NO
Left Rear	Fortune	8		NO	YES	NO
Left Rear Inside	Fortune	8		NO	YES	NO
Right Front	Track master	16				
Right Rear	Fortune	8		NO	YES	NO
Right Rear Inside	Fortune	8		NO	YES	NO
Tire Size				NO	YES	NO
Spare			Tires Needed			
NO			NO			

Tire Size - TIRES

225/70R19.5

MARKETING PHOTOS (7)





LINE ITEM PHOTOS (14)

Bumper



Front bumper is bent (Functional)



Eng. Enclose Hood / Stack




Hood has stress cracks (Functional) Left headlight bezel is broken taped together



Inspection Sticker Dated

YES



Air Conditioner



Vent temperature 50° ambient
temperature 78°



Heater



Vent temperature 110° ambient
temperature 76°



Interior Lights



Interior light not working



Seat Cushion / Arm Rest



Driver bottom seat cushion is
ripped



Emissions Decal

YES



LIGHTS



License plate light not working



TRAILER BRAKES

YES



Anti-Freeze Color

Red

