










Wheel Loader Inspection Report

Inspection Date: 6/6/2024

MACHINE DETAILS									
Manufacturer:AA	Model:950M	S/N:0J1S03815							
Year:2021	Eng S/N:J7A14686	Trans S/N:TS401784							
SMU/Hrs:3700	Hours Date:6/2024								
Last Schedule:	Last CTS:	Last PM:							
Date Oil Sample Sent to Lab:6/6/2024	Oil Sample:Engine/Trans./Hyd.								
Recommendations:									
WHEEL LOADER CONFIGURATION									
ECM Download: Yes	ROPS: Enclosed	Product Link: Includes							
EROPS: Yes	OROPS: No	Air Conditioning: No							
Heater: Yes	Counterweight: Yes	Coupler, Quick: No							
Bucket: Yes	Bucket Size: 4.75 CYD	Edge: No							
Teeth: No	C/E or Teeth: C/E	Auxiliary Hydraulics: No							
Boom Group: Standard	Engine Tier Rating: Tier 4	High Lift: No							
Stick Steer: No	Ride Control: Yes	Fast Fill: No							
Auto Shift: Yes	Oil Change System: Yes	Anti-Theft System: No							
Product Link: Yes	Supplemental Steer: No	Weight System: Yes							
Tire Size: 23.5R25	Comment:								
GENERAL APPEARANCE									
CODE	REMARKS								
Radiator Grill	Good								
Shroud	Good								
Engine Enclosure	Good								
Hood / Stack	Good								
Fuel Tank	Good								
Fenders	Good								
Crankcase Guard	Good								
Battery Box	Good								
Front Frame	Good								
Rear Frame	Good								
Diff Supports	Good								
Counterweight	Good								
Pre-Cleaner Bowl	Not Applicable								
Cab	Good								
Canopy	Not Applicable								
Steps / Ladder	Good								
Grab Irons	Good								
Paint	Fair	Weather faded							
Sheet Metal	Good								
Guards / Screens	Good								
SOS Taken	Yes								
Cleaning Required	Yes								
Notes									
									
									
									
									
SAFETY ITEMS									
CODE	REMARKS								
Safety Decals In Place	Yes								
Safety Decals Legible	Yes								
Articulation Safety Bar	Good								
Horn	Good								
ROPS	Yes								
Notes									

Wheel Loader Inspection Report

										
GAUGES, OPERATOR STATION, CONSOLE										
CODE	REMARKS									
Dash Console	Good									
Hour Meter	Good									
Gauges	Good									
Switches	Good									
Wipers	Good									
Air Conditioner	Fair	Blowing cool air not cold. Duct temp 50 Ambient 64								
Heater	Good									
Radio / Speakers	Good									
Interior Lights	Good									
Seat Cushions	Good									
Arm Rests	Good									
Floor Boards	Good									
EMS Panel / Warnings	Good									
Doors	Good									
Door Latches	Good									
CMS Panel	Good									
Glass / Mirrors	Good									
Seat Belt	Good									
Hydraulic Controls	Good									
Sound Proofing	Yes									
Back-up Alarm	Yes									
Parts Book	Yes									
Safety Manual	Yes									
O&MM	Yes									
Notes										
										
										
										
ENGINE										
CODE	REMARKS									
Oil Leaks	No									
Blow By	No									
Knocking	No									
Compression In Radiator	No									
Water In Oil	No									
Fluid Levels OK?	Yes									
EPA Decal	Yes									
Anti-freeze Color	Red									
Oil Pressure (H/L/W)	85/53									
Smoke (B/D/L/W)	Clear									
Operating Condition	Good									
Turbocharger / Blower	Good									
Fuel Injection System	Good									
Governor	Good									
Engine Supports	Good									
Air Cleaners	Good									
Exhaust / Muffler	Good									
Belts / Pullys	Good									
Oil Filter Condition (Cut)	Not Applicable									
Notes										

Wheel Loader Inspection Report



TRANSMISSION

CODE	REMARKS
Case	Good
Seals	Good
Torque Converter	Good
Universal Joints	Good
Temp / Pressure Guages	Good
Drive Shaft	Good
Lines / Fittings	Good
Oil Filter Condition (Cut)	Not Applicable
Cooler	Good
Operating Condition	Good
Transmission - Noisy	No
Leaks	No
Notes	



COOLING SYSTEM

CODE	REMARKS
Radiator	Good
Coolers	Good
Hoses	Good
Water Pump	Good
Fan	Good
Fan Drive	Good
Leaks	No
Notes	



BRAKES





CODE	REMARKS
Type (Wet, Dry)	Wet
Drums / Rotors	
Control Valve	Good
Lines	Good
Master Cylinder	Not Applicable
Compressor	Not Applicable
Brake Linkage	Not Applicable
Pedal	Good
Parking Brake	Good
Hydraulic Pumps	Good
Accumulators	Good
Notes	



STEERING

CODE	REMARKS
Steering Linkage	Good
Articulation Pins & Bushings	Good
Steering Cylinder	Good
Supplemental Steering	Not Applicable
Pumps	Good
Valves	Good
Hand Metering Unit	Good
Steering Wheel Tilt / Extend	Good

Wheel Loader Inspection Report

Lines / Fittings	Good								
Notes									
									
FINAL DRIVES									
CODE		REMARKS							
Wheel Lugs & Rims	Good								
Rear Final Drives	Good								
Rear Axle	Good								
Front Final Drives	Good								
Front Axle	Fair	Axle seals appear wet - Need to clean and reexamine.							
Differentials	Good								
Oscillation	Good								
Trunnions	Good								
Leaks	No								
Notes									
									
HYDRAULICS									
CODE		REMARKS							
Operating Condition	Good								
Tank	Good								
Pumps & Valves	Good								
Hose Lines	Good								
Control Linkage	Good								
Bucket Kickouts	Good								
Lift Cylinders	Fair	Left cylinder seeping oil at wiper seal							
Tilt Cylinders	Good								
Attachment Cylinder	Not Applicable								
Filter Condition (Cut)	Not Applicable								
Leaks	No								
Notes									
									
ELECTRICAL, STARTING AND CHARGING SYSTEM									
CODE		REMARKS							
Batteries / Cables	Good								
Starter	Good								
Alternator	Good								
Wiring	Good								
Pre-Heater	Good								
Lighting	Good								
Ether Aid	Yes								
Block Heater	Yes								
Notes									
									
BUCKET									
CODE		REMARKS							
Cutting Edges	Good								
Teeth / Adapters	Not Applicable								
Bucket Bottom	Good								
Bucket Sides	Good								
Bucket Spill Guard	Good								
Bucket Linkage	Good								
Loader Pins & Bushings	Good								
Loader Frame	Good								

Wheel Loader Inspection Report

Segments	Good	
Quick Coupler	Not Applicable	
Bucket Floor	Good	
Multipurpose Cylinders	Not Applicable	
Bucket Capacity	4.75	
Bucket S/N	G9H09180	
Notes		



ATTACHMENTS / WORK TOOLS

CODE	REMARKS
Lift Boom	No
Angle Broom	No
Vibratory Compactor Plate	No
Asphalt Cutter	No
Hydraulic Sweeper	No
Material Handling Arm	No
Grapple	No
Forks	No
Other	No
Other	No
Notes	

TIRES

	MAKE S/N	TREAD DEPTH 1/32"	% LIFE LEFT	RECAPPED	TREAD CUT/CHUNKS	SIDE CUTS SECTIONS
Right Front	Firestone W1S003049	64.00	94.12	No	No	No
Right Rear	Firestone W1S002409	68.00	100.00	No	No	No
Left Rear	Firestone W1S002411	64.00	94.12	No	No	No
Left Front	Firestone W1S002407	64.00	94.12	No	No	No
Tire Size	23.5/25					
Spare	No					
Average Life Left	95.59					
Notes						
Tires Needed						



SERVICE

CODE	REMARKS
Service Needed	

GENERAL REPAIRS AND REMARKS

Repairs Needed: Left lift cylinder seeping at wiper seal. Cooler and radiator externally plugged with debris. Condenser externally plugged with debris. A/C system blowing cool, not cold. Front axle seals appear to be wet. Need to clean and recheck
General comments: Machine is in good condition for age and hours.



Wheel Loader Inspection Report

