

2006 GODWIN PUMPS CD150M DRI-PRIME PUMP WATER PUMPS / TRASH PUMPS

INSPECTION DETAILS

Inspection Type	Consignment
Inspection Form	Standard
Inspection #	10221122
Inspection Status	Inspected
Created	08/05/25 14:34:00
Updated	08/06/25 11:49:23
Created By	Earl, Ryan
Inspector	Earl, Ryan
Engine Serial #	PE4045D606939
Serial #	46326
SMU / Hours	3,252
Location	BRAWLEY, CA 92227, United States



FEATURES

General

- **6 INCH SUCTION AND DELIVERY PUMP**
- **80 HP ENGINE**
- **EPA CERTIFIED FOR DIESEL FUEL**
- **Jack Stands**
- **JOHN DEERE 4045DF270B ENGINE**
- **Trailer Mounted**

NOTES

INSPECTION FOR CONSIGNMENT. GODWIN SERIAL NUMBER PLATE WAS SUN ROT AND PEELING, UNSURE ABOUT ACTUAL SERIAL NUMBER AND MODEL YEAR. MODEL YEAR ALIGNED WITH ENGINE MODEL YEAR.

CONDITION Good Fair Poor

Approved Repair

GENERAL APPEARANCEAxles
 1 Battery Box
 1 Fuel Tank
Hitch/Tongue
 1 Main Frame Welds
Paint


FADED AND OXIDIZED.

Plastic
Radiator Grill & Shroud
 2 Sheet Metal
Trailer Jack Stand
 2 Wheel Lugs
Wheels
Cleaning Required
YES
WASH FOR TRANSPORT AND
DELIVERY.S.O.S. Taken
YES
ENGSERVICE?
YES
NEEDS 500 HOUR PM SERVICE.**SAFETY ITEMS**Safety Chains Hooks
 1Safety Decals In Place
NO
NEEDS NEW SAFETY DECALS
AND SERIAL NUMBER DECAL.Safety Decals Legible
NO**OPERATOR STATION**Meter
 7

SERVICE NEEDED, ACTIVE CODES.

Current O&MM
YES 1 Current Parts Manual
NO

ENGINE

Belts / Pulleys


1 Engine Supports


Exhaust / Muffler


1

Fuel Injection System


2 Governor


Overall Operating Condition


4

FUEL LEAKS OBSERVED.

Turbocharger / Blower


Blow By
NO

Compression in Radiator
NO

Emissions Decal
YES

1

Fluid Levels OK?
YES

Has Engine been rebuilt?
NO

Knocking
NO

Oil Leaks


ENGINE OIL PAN STARTING TO
SEEP, NEEDS MONITORED.

Anti-Freeze Color
RED

Fuel Level
NORMAL

Oil Pressure (H/L/N)
NORMAL

Smoke (B/D/L/W)
NORMAL

COOLING SYSTEM

Coolers


Fan


Hoses


WEATHERED, NO LEAKS OBSERVED.

Radiator


1 Water Pump


Leaks
NO

ELECTRICAL, STARTING AND CHARGING SYSTEM



TIRES

Make / Serial#	Tread Depth in 1/32"	% Life Remaining	Recapped	Tread Cuts/Chunks	Side Cuts Section
Left Front	DURO LT	3	38	NO	YES
Right Front	DURO LT	3	38	NO	YES

Spare
NO

Tires Needed
YES
NEW TIRES NEEDED.

Average Life Remaining - TIRES
38%

Tire Size - TIRES
205/75D15

COMMENTS, MISC. REPAIRS, GENERAL REMARKS

comment 1



WATER PUMP COMPONENTS.

MARKETING PHOTOS (19)







