

2019 CAT 140M3AWD MOTOR GRADERS

INSPECTION DETAILS

Inspection Type	Consignment
Inspection Form	Standard
Inspection #	10225757
Inspection Status	Completed
Created	08/25/25 11:24:34
Updated	09/03/25 11:04:07
Created By	Fuentes, David A.
Inspector	Fuentes, David A.
Reviewers	Fuentes, David A.
Salesperson	Schultis, Derrick R.
Transmission Serial #	SS601510
Engine Serial #	SYE33635
Serial #	N9J01221
SMU / Hours	9,818
Location	Tempe, AZ, United States




FEATURES

General

- Air Conditioner
- Cab Profile - Low
- Differential Lock
- Hydraulic Valves
- Moldboard Size - 14'
- Radio - Bluetooth
- Steering Type - Joystick
- Air Suspension Seat
- Circle Clutch
- Drive - All Wheel
- Lighting
- Product Link
- Ripper - Multi-Shank
- Throttle Lock
- Auto Shift
- Defroster Fan
- Guard, Transmission
- Mirrors
- Pushblock
- ROPS - Enclosed
- Tire Size

Attachments

- Scarifier

CONDITION Good Fair Poor Approved Repair**GENERAL CONDITION**Body
Frame - GENERAL CONDITION
General
ET Product Status Report
Download
YESMachine Starts and is Operable
YESTires are Aired Up and Drivable
YESVisible Oil Leaks
NO**GENERAL APPEARANCE**Battery Box
Cab or Canopy
Crankcase Guard / Transmission
Guard
Decals
Draw Bar
Engine Enclosures
Front Frame Welds
Fuel Tank
Grab Irons
Hood
Paint
Plastic (Exterior)
Plastic covers in front cab are missing
hardwareRadiator Grill
Rear Frame Welds
Sheet Metal
Steps / Ladder
Cleaning Required
NO

SAFETY ITEMS

Back Up Alarm



Camera(s)



Fire Extinguisher



Horn



ROPS



Seat Belt / Date



Seat belts date tag are expired

Secondary Exit



Parking Brake Functioning

YES

ROPS Certification Plate

YES

Safety Decals In Place

YES

Safety Decals Legible

YES

Safety Locks / Pins

YES

Service Brakes Functioning

YES

OPERATOR STATION

Air Conditioner



1

Armsrests



Cab Filter / Heat Vent Louvres



Vent temperature 49° Ambient
temperature 93°

Dash Console



Door Latches / Hinges / Seals



Left door seal is ripped tape together

Floor Boards / Mats



Gauges



Headliner



Heater / Defroster



Vent temperature 129° Ambient
temperature 94°

Hour Meter - GAUGES,
OPERATION STATION, CONSOLE



Hydraulic Controls



Interior Lights



Interior Plastic / Fabric



Mirrors



Monitoring Display



Radio

AM/FM/ Bluetooth speaker

Seat Cushions / Suspension /
Type

Bottom seat cushion has small hole
bunt in it

Switches


Transmission Controls


Windows


Windshield Wipers


1

Current O&MM
YES

1 Current Safety Manual
YES

1 Sound Proofing
YES

ENGINE

Belts / Pulleys - ENGINE


Engine Oil Level / Condition


Engine Supports / Mounts


Exhaust / Muffler / Stack


Fuel Injection System


Governor


Intake / Air Filters


Operating Condition - ENGINE


Turbocharger / Blower


Apparent Other Engine Damage
NO

Blow By
NO

Emissions Decal Legible
NO

Fuel Leaks
NO

Has Engine been rebuilt?
NO

Knocking
NO

Oil Leaks
NO

Pre Lube System
NO

Service Needed
YES

Water in Oil
NO

Engine S/N
SYE33635

Oil Pressure (H/L/N)
Normal

Smoke Color (B/D/L/W)
Normal

EMISSIONS

Aftertreatment Heat Shields /

Guards



DEF Lines / Wiring



Diesel Particulate Filter (DPF)

Condition / Service Hours



Aftertreatment System Codes

NO

Leaks / Type

NO

COOLING SYSTEM

Anti-Freeze Level / Color /

Condition



Red

Belts / Pulleys - COOLING

SYSTEM



Coolers



Fan



Fan Drive / Type



Fan Shrouds / Guards



Hoses / Tubes



Radiator



Water Pump



Compression in Radiator

NO

Coolant Leaks

NO

Oil in Anti-Freeze

NO

Standard Radiator

YES

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator



Batteries / Cables



Pre-Heater



Product Link / Condition



Starter



Wiring



Work Lights



Active Codes

NO

Jump Start Terminal

YES



Signal Lights

YES

TRANSMISSION

Case - TRANSMISSION



Controls - TRANSMISSION



Cooler



Lines / Fittings - TRANSMISSION



Operating Condition - TRANSMISSION



Pump - TRANSMISSION



Seals



Temp / Pressure Gauges



Transmission - Forward Shifts



Transmission - Reverse Shifts



Valves



Auto Shift

YES

Leaks - TRANSMISSION

NO

Powershift

YES

Transmission - Noisy

NO

ALL WHEEL DRIVE

All Wheel Drive Lines / Fittings



All Wheel Drive Operating Condition



All Wheel Drive Valve



Controls / Settings



Drive Motors



Final Drives / Oil Levels



Pump



STEERING

Articulate P & B



King Pins



Lines / Fittings



Steering Column / Tilt



Steering Cylinder



Steering Frame



Steering Linkage



Steering Operating Condition



Steering Pump



Steering Valve



Tie Rods / Rod Ends



Wheel / Joystick



Joystick

Wheel Lean Cylinder - STEERING



BRAKE

Accumulators



Brake Linkage



Control Valve



Lines



Parking Brake Operation



Pedal



Service Brake Operation



DRIVECHAIN / TANDEMS

Differential



Differential Lock / Operation



Drivetrain / Tandem Leaks



Planetary



Tandem Housing / Drive Chains



Wheel Lugs & Rims



HYDRAULICS

Blade Cushion



Circle Drive Box



Circle Side Shift Cylinder



Cylinder Mounts / Pins



Hydraulic Lines / Fittings



Hydraulic Pump



Hydraulic Valves



Lift Cylinders



Linkage



Operating Condition -

HYDRAULICS



Saddle Pin / Actuator



Side Shift Cylinder



Tank / Sight Glass / Cap



Tip Cylinder



Leaks - HYDRAULICS

NO

BLADE

Circle A Frame



Circle Frame



Circle Shoes / Inserts



Cutting Edge



Cylinder Balls / Caps



Face / Moldboard



Lift and side shift cylinder trunnions and inserts have movement. Yokes have some movement (Functional)

Frog / Base Edge



Moldboard Tip Brackets / Inserts



Ring Gear



Saddle



Tip Bracket Pivots / Bearings



RIPPER

Beam



Brackets / Studs



Cylinders



Frame



Lines / Fittings - RIPPER



Pins / Bushings



Shanks / Ripper (GET)



All teeth worn needs replaced



Shanks / Scarifier (GET)



All teeth worn no replaced



TIRES

	Make / Serial#	Tread Depth in 1/32"	% Life Remaining	Recapped	Tread Cuts/Chunks	Side Cuts Section
Left Center	Galaxy	26	76.47	NO	YES	NO
Left Front	Maxam	32	94.12	NO	YES	NO

Left Rear	Galaxy	26	76.47	NO	YES	NO
Right Center	Galaxy	26	76.47	NO	YES	NO
Right Front	Maxam	30	94.12	NO	YES	NO
Right Rear	Galaxy	27	88.24	YES	YES	NO

Radial
YES

Average Life Remaining - TIRES
84.31

Tire Size - TIRES
17,5R25

MARKETING PHOTOS (28)









