

# 1996 CAT 325L TRACK EXCAVATORS

## INSPECTION DETAILS

Inspection Type	Consignment
Inspection Form	Standard
Inspection #	10226541
Inspection Status	Inspected
Created	08/27/25 13:36:40
Updated	08/28/25 10:42:32
Created By	Fuentes, David A.
Inspector	Fuentes, David A.
Reviewers	Fuentes, David A.
Salesperson	Schultis, Derrick R.
Engine Serial #	98Z14994
Serial #	7LM01385
SMU / Hours	8,979
Location	Globe, AZ, United States



## FEATURES

### General

- Air Conditioner
- Car Body - Standard
- Engine Enclosures
- Mirrors
- Auxiliary Hydraulics Pressure
- Coupler - Quick
- Hand and Foot Control
- Stick
- Boom - 1 Piece
- Coupler Type - Hydraulic
- Lighting

### Attachments

- Grapple

## CONDITION

●●● Good

●● Fair

● Poor

Approved Repair

## GENERAL CONDITION

Body  
●●●

Frame  
●●●

General  
●●

Machine is infected with pack rats it has a lot of rat feces

ET Product Status Report  
Download  
NO

Machine Starts and is Operable  
YES

Visible Oil Leaks  
YES  
Multiple oil leak

## GENERAL APPEARANCE

Bumper  
●●

Both sides of bumper have multiple dents and bumper under windshield is broken.

●10 Car Body  
●●●

Counterweight  
●●●

Crankcase Guard / Battery Box  
●●  
Multiple panels under the house are bent and or missing

Decals  
●●  
All decals are faded and scratched

Eng. Enclose Hood / Stack  
●●●

Engine Doors  
●●  
Right side pump door is bent

Fuel Tank  
●●  
Fuel cap breather is broken

●1 Grab Irons  
●●  
Left front grab iron is bent

Hood  
●●●

Main Frame Welds  
●●●

Paint  
●●  
Paint is faded and scratched

Pre-Cleaner Bowl  
●●●

Radiator Grill & Shroud  
●●●

Sheet Metal  
●●●

Steps / Ladder  
●●  
All step on car body is bent

## Cleaning Required

**YES**

Machine has a lot of rat feces  
throughout machine

## SAFETY ITEMS

Horn



Horn not working

Seat Belt / Date



Seat belt is outdated

Travel Alarm



ROPS

**YES**

Safety Decals In Place

**NO**

Safety Decals Legible

**NO**

## OPERATOR STATION

Air Conditioner



A/C is blowing hot and smell like rat  
urine

Armrests



Door Latches / Hinges / Seals



Door hinges have been welded. Door  
is bent and hard to open and door  
seal is coming off

Floor Boards / Mats



Floor mat has holes ( Functional )

Gauges



Headliner



Head liner is dirty ( Functional )

Heater / Defroster



Hour Meter - GAUGES,  
OPERATION STATION, CONSOLE



8979

Hydraulic Controls



Interior Lights



Interior light not working

Mirrors



Monitoring Display



Film on monitor is peeling

Seat Cushions / Suspension /  
Type



Both seat cushions are ripped



Switches



Travel Controls (Type)



Windows



Roof hatch is missing right side and  
rear window are to see through



Windshield Wipers



Windshield washer reservoir is broken

Current O&MM

**NO**

No OMM

Current Safety Manual

**NO**

No safety manual

---

## ENGINE

Belts / Pulleys - ENGINE



Engine Oil Level / Condition



Valve cover is leaking

1

Engine Supports / Mounts



Exhaust / Muffler / Stack



Fuel Injection System



Governor



Intake / Air Filters



Operating Condition - ENGINE



Turbocharger / Blower



Apparent Other Engine Damage

**NO**

Blow By

**NO**

Fuel Leaks

**NO**

Knocking

**NO**

Oil Leaks

**NO**

Pre Lube System

**NO**

Service Needed

**YES**

Water in Oil

**NO**

Engine S/N

98Z14994

Oil Pressure (H/L/N)

Normal

Smoke Color (B/D/L/W)

Normal

---

## COOLING SYSTEM

Anti-Freeze Level / Color /

Condition



Belts / Pulleys - COOLING

SYSTEM



Coolers



Fan



Fan Shrouds / Guards



Hoses / Tubes



Radiator



Water Pump



Compression in Radiator  
**NO**

Coolant Leaks  
**NO**

Oil in Anti-Freeze  
**NO**

Standard Radiator  
**YES**

---

## ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator  


Batteries / Cables / Master  
Disconnect  


Lighting  


Pre-Heater  


Starter  


Wiring  


---

## HYDRAULICS

Boom Cylinder  
  
Right side boom cylinder is leaking

Bucket Cylinder  


Control Linkage  


Hose Lines  


Hydraulic Swivel  


Operating Condition -  
HYDRAULICS  


Pump Drive  


Pumps & Valves  


Rotex  


Stick Cylinder  


Swing Gear  


Swing Motors  


Tank  


Travel Motors  


---

## ATTACHMENTS / WORK TOOLS

Grapple  


**YES**

NPK grapples. Leak on grapple is  
bent

---

## BOOM

**Boom Condition****Boom Pins****Pins & Bushings - BOOM****Boom Length (Actual Length)**

20' 2"

**STICK****Pins & Bushings - STICK****Stick Conditions****Stick Pins****Stick Length**

10'6"

**UNDERCARRIAGE**

	Measurement (L)	% Worn (L)	Total Potential Hours (L)	Measurement (R)	% Worn (R)	Total Potential Hours (R)
Carrier Rollers Front	6.72			6.72		
Idlers Front	.82	48		.82	48	
Links	4.42	65		4.42	65	
Pins & Bushings (External)	2.50	24		2.50	24	
Track Roller 1	.82	35		.82	35	
Track Shoe Grouser Height	.72	42		.72	42	

**Track Frame - Left****Track Frame - Right****Pins & Bushings Turned?****NO****FINAL DRIVES****Housings, Left****Housings, Right****Planetaries / Differential, Left**

Planetaries / Differential, Right



## MARKETING PHOTOS (17)





