



2007 CAT  
CS-433E  
VIBRATORY SINGLE DRUM SMOOTH

INSPECTION DETAILS

Inspection Type	Consignment
Inspection Form	Standard
Inspection #	10227763
Inspection Status	Inspected
Created	09/02/25 14:45:02
Updated	09/02/25 21:48:28
Created By	Gabriel, James P.
Inspector	Gabriel, James P.
Engine Serial #	CRS45115
Serial #	ASR00950
SMU / Hours	9,999
Location	Brawley, CA 92227, United States



FEATURES

General

- **CONTROL, SINGLE FREQUENCY**
- **STANDARD DRUM**  
*Smooth Drum 66" Width*
- **Lighting**
- **STEEL DRUM SCRAPER**
- **ROPS - Open**

Regulatory

- **Emissions Level**  
*Tier Two*
- **Tier 2 Compliant**

Attachments

- **Leveling Blade**

CONDITION

Good

Fair

Poor

Approved Repair

GENERAL CONDITION


Body <div><div></div><div></div><div></div></div>	Frame <div><div></div><div></div><div></div></div>	General <div><div></div><div></div><div></div></div>
ET Product Status Report Download <b>NO</b>	Machine Starts and is Operable <b>YES</b>	S.O.S. (All Compartments) <b>NO</b> Engine and Hydraulic
Tires are Aired Up and Drivable <b>YES</b>	VIDS/VIMS Download Available <b>NO</b>	Visible Oil Leaks <b>NO</b>

GENERAL APPEARANCE

Cab or Canopy <div><div></div><div></div><div></div></div> Canopy	Decals <div><div></div><div></div></div> Machine model decals are faded.	<div><div></div><div></div><div></div></div> 2Eng. Enclose Hood / Stack <div><div></div><div></div><div></div></div>
Front Frame <div><div></div><div></div><div></div></div>	Fuel Tank <div><div></div><div></div><div></div></div>	Grab Irons <div><div></div><div></div><div></div></div>
Guards / Screens <div><div></div><div></div><div></div></div>	Paint <div><div></div><div></div></div> Paint is faded.	Radiator Grill & Shroud <div><div></div><div></div><div></div></div>
Rear Frame <div><div></div><div></div><div></div></div>	Sheet Metal <div><div></div><div></div><div></div></div>	Steps / Ladder <div><div></div><div></div><div></div></div>
Cleaning Required <b>YES</b> Clean machine.		

SAFETY ITEMS

Camera(s) <div><div></div><div></div><div></div></div>	Horn <div><div></div><div></div><div></div></div>	ROPS <div><div></div><div></div><div></div></div>
---	--	--

Seat Belt / Date  
  
Seat belt expired. May 2007  
installation.

1 Secondary Exit  


Back Up Alarm  
**YES**



Safety Decals In Place  
**YES**

Safety Decals Legible  
**YES**




Safety Locks / Pins  
**YES**

---


## OPERATOR STATION

Armrests  
  
Left control wrist rest is weathered  
and torn.




1 Dash Console  


Floor Boards / Mats  





Gauges  


Hour Meter - OPERATOR  
STATION  
  
Meter display is not functioning.  
Actual hours unknown.

Hydraulic Controls  


Interior Plastic / Fabric  


Pans/Guards  


Seat Cushions / Suspension /  
Type 1  
  
Seat bottom cushion is torn.

Switches  





Current O&MM  
**NO**  
No manuals




Current Parts Manual  
**NO**



Current Safety Manual  
**NO**

---

## ENGINE

Belts / Pulleys  


Engine Oil Level / Condition  


Engine Supports / Mounts  
  
Engine mount bushings are  
weathered and cracked.

Exhaust / Muffler / Stack ●●●	Fuel Injection System ●●●	Governor ●● Engine speed surges at low idle.	1
Intake / Air Filters ●●●	Operating Condition ●●●	Turbocharger ●●●	
Blow By NO	Fuel Leaks NO	Knocking NO	
Oil Leaks NO	Water in Oil NO		
Oil Pressure (H/L/N) Normal	Smoke Color (B/D/L/W) Normal		

COOLING SYSTEM

Anti-Freeze Level / Color / Condition ●●●	Belts / Pulleys - COOLING SYSTEM ●●●	Coolers ●●●	
Fan ●●●	Fan Drive / Type ●●●	Fan Shrouds / Guards ●●●	
Hoses / Tubes ●●●	Radiator ●●●	Water Pump ●●●	
Compression in Radiator NO	Coolant Leaks NO	Oil in Anti-Freeze NO	
Standard Radiator YES			

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator ●●●	Batteries / Cables / Master Disconnect ●●●	Starter / Type ●●●	
-------------------	---	-----------------------	--

Wiring



Has a wire harness dangling from canopy that needs secured.



1

Work Lights



Block Heater

**NO**

Ether Aid

**NO**

Signal Lights

**NO**

**TRANSMISSION**

Drive Type

Hydrostatic Two speed

**STEERING**

Articulate P & B



Pivot P & B Trunnions



Steering Cylinder



Steering Linkage



Steering Valves / Pumps



**HYDRAULICS**

Cylinders



Hose Lines



Has a couple hoses below cab that are wet.



3

Propel Motor



Propel Pump



Tank



Vibratory Motor



Vibratory Pump



**DRUM**

Drum Drive Planetaries



Drum Hubs



Drum Scrapers



Steel Drum Scraper

Drum Surface



Isolators



Vibratory System



Pad Feet Shells  
**NO**

AXLES / FINAL DRIVES

Differential  
●●●

Differential Supports  
●●●

Final Drives  
●●●

Trunion  
●●●

Wheel Lugs & Rims  
●●●

Leaks  
**NO**

Magnetic Plugs Removed &  
Checked?  
**NO**

TIRES

	Make / Serial#	Tread Depth in 1/32"	% Life Remaining	Recapped	Tread Cuts/Chunks	Side Cuts Section
Left Rear	Titan	16	45.71	<b>NO</b>	<b>NO</b>	<b>NO</b>
Right Rear	Titan	17	48.57	<b>NO</b>	<b>NO</b>	<b>NO</b>

Average Life Remaining - TIRES  
47.14

Tire Size - TIRES  
14.9-24

MARKETING PHOTOS (24)

