



2016 CATERPILLAR 938M WHEEL LOADER

PRICE

\$204,600 USD

WHOLESALE

\$0 USD



SALES INFORMATION

| | | | |
|-------------|-------------------------|--------------|-----------|
| Catalog # | 4377010 | Serial # | J3R02862 |
| SMU / Hours | 250 | Status | Used |
| Rating | As-Is | Availability | Available |
| Location | Eloy, AZ, United States | | |

FEATURES

| | | |
|---------------------|--------------------------|--------------------------------|
| • AIR CONDITIONER | • AM FM CD RADIO | • BEACON |
| • BLUETOOTH | • BOOM, GP | • BUCKET |
| • COUPLER, QUICK | • DIFFERENTIAL, STANDARD | • EROPS |
| • FIRE EXTINGUISHER | • FORKS | • LIGHTING |
| • PRODUCT LINK | • STEER, COMMAND | • ULTRA LOW SULFUR DIESEL FUEL |

CONDITION Good Fair Poor**GENERAL CONDITION** Body Frame General

YES ET Download Available

YES Machine Starts and is Operable

YES Tires are Aired Up and Drivable

GENERAL APPEARANCE Bumper Cab or Canopy Counterweight Crankcase Guard / Battery Box Decals Differential Supports Eng. Enclose Hood / Stack Fenders Front Frame Fuel Tank Grab Irons Paint Plastic Radiator Grill & Shroud Rear Frame Sheet Metal Steps / Ladder

YES Cleaning Required

Machine is dirty from training

YES S.O.S. Taken

Engine and hydraulic

SAFETY ITEMS Brake Hold Fire Extinguisher Glass / Mirrors Horn Parking Brake - SAFETY ITEMS ROPS

YES Back Up Alarm Functioning

YES Brakes Functioning

YES ROPS

YES Safety Decals In Place

YES Safety Decals Legible

GAUGES, OPERATOR STATION, CONSOLE Air Conditioner Dash Console Door Latches

Vent temperature 48°. Ambient temperature 70°

 Door Latches & Hinges Doors EMS Panel / Warnings Floor Boards Floor Mats Gauges Glass/Mirrors Heater
Vent 101°. Ambient 65° Interior Lights Meter Product Link Seat Belt - GAUGES, OPERATOR STATION, CONSOLE
8/16

●●● Seat Cushion / Arm Rest

●●● Windshield Wipers

YES Back Up Alarm

YES Current Safety Manual

Diesel Exhaust Fluid (DEF) Level -
GAUGES, OPERATOR STATION,
CONSOLE
81%

ENGINE

●●● Air Cleaners
Air filter is dirty

●●● Exhaust / Muffler

●●● Governor

●●● Turbocharger / Blower

NO Apparent Other Engine
Damage

YES Engine Oil Level Full

NO Fuel Leaks

NO Water in Oil

Oil Pressure (H/L/N)
Normal

COOLING SYSTEM

●●● Belts / Pulleys - COOLING
SYSTEM

●●● Fan Drive

●●● Radiator

NO Leaks - COOLING SYSTEM

ELECTRICAL, STARTING AND CHARGING SYSTEM

●●● Alternator

●●● Lighting

●●● Switches

YES Current O&MM

YES ROPS Certification Plate

Fuel Level - GAUGES, OPERATOR
STATION, CONSOLE
100%

●●● Belts / Pulleys - ENGINE

●●● Fuel Injection System

●●● Operating Condition - ENGINE

NO Blow By

YES EPA Decal

NO Knocking

Smoke (B/D/L/W)
Normal

●●● Coolers

●●● Hoses

●●● Water Pump

NO Leaks - COOLING SYSTEM 1

●●● Batteries / Cables

●●● Starter Electric

●●● Windows

YES Current Parts Manual
CD

YES Sound Proofing

●●● Engine Supports

●●● Fuel System

●●● Turbocharger

NO Compression in Radiator

YES Fluid Levels OK?

NO Oil Leaks

●●● Fan

●●● Hoses & Tubes - COOLING
SYSTEM

●●● Beacon

●●● Wiring

YES Block Heater

YES Ether Aid
With canister

TRANSMISSION

●●● Controls - TRANSMISSION

●●● Operating Condition -
TRANSMISSION

●●● Temp / Pressure Gauges

●●● Transmission - Forward Shifts

●●● Cooler

●●● Pump - TRANSMISSION

●●● Torque Converter -
TRANSMISSION

●●● Transmission - Reverse Shifts

●●● Drive Shaft

●●● Seals

●●● Transmission

●●● Universal Joints -
TRANSMISSION

NO Leaks - TRANSMISSION

NO Transmission - Noisy

STEERING

●●● Articulate P & B

●●● Pumps

●●● Steering Valves / Pumps

●●● Hand Metering Unit

●●● Steering Cylinder

●●● Steering Wheel Tilt / Extend

●●● Lines / Fittings - STEERING

●●● Steering Linkage

●●● Valves

BRAKE

●●● Accumulator

●●● Brake Linkage

●●● Leaks - BRAKE

●●● Parking Brake - BRAKE

●●● Type (Wet, Dry)
Wet

●●● Accumulators

●●● Control Valve

●●● Lines

●●● Pedal

●●● Brake Drums / Rotors

●●● Hydraulic Pumps

●●● Lines / Tubes

●●● Pump - BRAKE

YES Holds In Park

NO Leaks - BRAKE

Holding What Gear?

All

AXLE ASSEMBLIES

●●● Front Axle Housing

●●● Rear Axle Housing

●●● Wheel Lugs & Rims - AXLE
ASSEMBLIES

HYDRAULICS

●●● Accumulator Charge - Ride
Control

●●● Attachment Cylinder

●●● Bucket & Hoist Kickout

| | | |
|--------------------------------|---------------------|---------------------------------|
| ●●● Bucket Cylinder | ●●● Control Linkage | ●●● Hose Lines |
| ●●● Hoses & Tubes - HYDRAULICS | ●●● Lift Cylinders | ●●● Overall Operating Condition |
| ●●● Pumps & Valves | ●●● Tank | |

NO Leaks - HYDRAULICS

ATTACHMENTS / WORK TOOLS

YES Forks
62" forks

BUCKET

| | | |
|-------------------------------|------------------|-----------------------------|
| ●●● Bucket Bottom | ●●● Bucket Floor | ●●● Bucket Linkage - BUCKET |
| ●●● Bucket Linkage - BUCKET 1 | ●●● Bucket P & B | ●●● Bucket Sides |
| ●●● Cutting Edges | ●●● Loader Frame | ●●● Loader Pins & Bushings |
| ●●● Quick Coupler | | |

YES Standard Lift

Bucket Capacity
3.6yd. 107.4"

Bucket S/N - BUCKET
150702720

FINAL DRIVES

| | | |
|-------------------|----------------|--------------------------------------|
| ●●● Differentials | ●●● Front Axle | ●●● Oscillation |
| ●●● Rear Axle | ●●● Trunion | ●●● Wheel Lugs & Rims - FINAL DRIVES |

NO Leaks - FINAL DRIVES

TIRES

| | Make / Serial# | Tread Depth in 1/32" | % Life Remaining | Recapped | Tread Cuts/Chunks | Side Cuts Section |
|-------------|----------------|----------------------|------------------|----------|-------------------|-------------------|
| Left Front | Michelin | 38 | 82 | NO | YES | NO |
| Left Rear | Michelin | 38 | 82 | NO | YES | NO |
| Right Front | Michelin | 38 | 82 | NO | YES | NO |
| Right Rear | Michelin | 38 | 82 | NO | YES | NO |

NO Spare

Average Life Remaining - TIRES
82.43%

Tire Size - TIRES
20,5R25

COMMENTS, MISC. REPAIRS, GENERAL REMARKS

comment 1
First Inspection

comment 2
Final Inspection

comment 3
Install PLink and register to Empire

comment 4
Wash

comment 5
PM1 Service

PHOTOS (19)







