

2012 CAT

980K

WHEEL LOADER

INSPECTION DETAILS

Inspection Type	Marketing
Inspection Form	Wheel Loaders
Inspection #	10187077
Inspection Status	Completed
Created	03/06/25 17:20:19
Updated	09/02/25 17:04:25
Created By	Fuller, Scott U.
Inspector	Brady, John
Reviewers	Fuller, Scott U.
Salesperson	Brady, John
Stock #	E203031
Serial #	W7K01208
SMU / Hours	18,025
Location	Henderson, NV 89052, United States



FEATURES

General

- Air Conditioner
- Boom, GP
- Lift - Standard
- Product Link
- ROPS - Enclosed
- Auto Lube
- Counterweight
- Lighting
- Radio - AM FM CD Radio
- Steering Type - Joystick
- Auto Shift
- Engine Enclosures
- Mirrors
- Ride Control

Regulatory

- EPA Label
- Ultra Low Sulfur Diesel Fuel

Attachments

- Bucket
7.5 CYD

CONDITION

●●● Good

●● Fair

● Poor

Approved Repair

GENERAL APPEARANCE

Battery Compartment



Bottom Guards



Cab / Canopy



Counterweight



Engine Enclosure Panels



Fiberglass shroud in engine compartment is cracked.



Fenders



Both front fenders have damage.

Fiberglass



Several areas in rear fiberglass are cracked.

Front Frame



Fuel Tank



Has large dent in tank. Breather has been replaced.



Grab Handles / Handrails



Guards / Screens



Hood Panels



Various areas of damage to the hood.



Mud / Splash Guards



Paint & Decals



Plastic Covers



Various scrapes and gouges

Platforms



Radiator Enclosure / Grill



Rear Frame



Rear radiator hood panel is damaged in multiple areas, and the hood will not open.

Sheet Metal Panels



Steps / Ladder



Cleaning Required

NO

S.O.S. Taken

YES

Service Required?

NO

**SAFETY ITEMS**

Alternate Exit



Back-Up Alarm



Horn



Implement Safety Lockout



Rear View Mirrors



Reflectors / Reflective Labels



Missing the rear reflectors.

ROPS



Seat-Belt



Warning / Safety Labels



Various labels are missing and torn.

ROPS Certification Label

YES

GAUGES, OPERATOR STATION, CONSOLE

Air Conditioner



Cab Floor



Cab Interior Trim



Cab Storage Compartments



Consoles



Dash Console



Doors / Latches



Floor Boards



Gauges / Instrument Panel



Glass & Windows



Heater



Hour Meter



Small crack in LF window.

Interior Lights



Monitor / Warning Alarm



Product Link



Seat / Suspension / Arm Rests



Switches



Windshield Wipers



Seat back fabric is torn.

Rear blade needs replaced, water bottle is cracked

Cameras

YES

ECM Downloaded

YES



O&M Manual

YES

Codes have been cleared

Parts Manual

YES

Radio

YES

Safety Manual

YES

ENGINE

Air Cleaners	Belts & Pulleys	Engine Air Inlet
		
Engine Exhaust	 1 Engine Front / Rear Housings	Engine Operating Condition
		
Engine Pre-Cleaner	Engine Supports	Exhaust / Muffler
		 Signs of previous or current exhaust leak at turbo.
Fuel Lines & Filters	Governor	Turbocharger
		
Emission Label	Engine Blow-By?	Engine Noises?
YES	NO	NO
Engine Oil Leaks	 7 Fluid Levels OK?	Fuel Leaks
NO	YES	NO
Water In Engine Oil?		
NO		
Antifreeze Color?	Notes - ENGINE Excessive dirt build up under engine.	Oil Pressure (H/L/N)
Red		Normal
Smoke (B/D/L/W)		
Normal		

COOLING SYSTEM

Coolers	Engine Cooling Tubes & Hoses	Fan
		
Fan Drive	Radiator	Radiator Shroud / Fan Guard
		

Water Pump



Compression In Radiator?

NO

Cooling System Leaks

NO

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator



Battery & Wiring



Lighting



Starter



Wiring



Ether Starting Aid

YES

TRANSMISSION

Case-Transfer



Case-Transmission



Controls-Transmission



Cooler



Torque Converter



Transmission Oil Lines & Tubes



Leaks around transmission. Some lines have been repaired.

Transmission Operating

Condition



Transmission - Noisy

NO

Transmission Oil Leaks

YES

There are leaks around the transmission. Sold as is.

Notes - TRANSMISSION

Excessive dirt build up under transmission.

STEERING

Articulation Hitch Pins &

Bushings



Controls-Steering



Steering Cylinder



Steering Valves / Pumps



Articulation Lock Linkage



1

Articulation Stops



Hand Metering Unit



Steering Operating Condition



Steering Cylinder Pins & Bushings



Steering Oil Lines & Tubes



BRAKE

Brake Accumulators



Brake Control Valve



Brakes Holding Ability Test



Brakes Oil Lines & Tubes



Brakes Operating Condition



Park Brake Holding Ability Test



Pedal



Brake System Leaks

NO

HYDRAULICS

Bucket & Hoist Kickout



Controls-Hydraulic



Cylinder Pins & Bushings



Hydraulic Oil Lines & Tubes



1

Hydraulic Operating Condition



Lift Cylinders



Pumps & Valves



Ride Control Operation



Ride control is stiff.

Tank Hydraulic



Tilt Cylinders

1

Possible seepage around the wiper seals.

Hydraulic System Leaks

NO

BUCKET

Bucket Bottom



Bucket Floor



Bucket Pins & Bushings



Bucket Sides



Bucket Spill Guard



Cutting Edges



Edges will need to be flipped.

1

Loader Frame



Loader Pins & Bushings



Tilt Linkages



Tilt Linkages Pins & Bushings



Standard Lift

YES

FINAL DRIVES

Differential / Axle Mounts



Differentials



Drive Shafts



Front Axle



Front Final Drives



Oscillation



Rear Axle



Rear Final Drives



Trunion



Axles, Differentials, Finals-Leaks

NO

TIRES

	Make / Serial#	Tread Depth in 1/32"	% Life Remaining	Recapped	Tread Cuts/Chunks	Side Cuts Section
Left Front	Magna M-Terrain	55	76	NO	YES	YES
Left Rear	Magna M-Terrain	26	36	NO	YES	YES
Right Front	Magna M-Terrain	50	69	NO	YES	YES
Right Rear	Magna M-Terrain	26	36	NO	YES	YES

Rims / Wheels Condition



Tire Size - TIRES

29.5R25

MARKETING PHOTOS (13)





