

2025 CAT 420XE4ECIP BACKHOE LOADER

INSPECTION DETAILS

| | |
|-------------------|------------------------------------|
| Inspection Type | Marketing |
| Inspection Form | BACKHOE LOADERS |
| Inspection # | 10237509 |
| Inspection Status | Created |
| Created | 10/06/25 07:43:25 |
| Updated | 10/06/25 07:52:57 |
| Created By | Fuller, Scott U. |
| Inspector | Heath, Jason |
| Stock # | E601309 |
| Serial # | H9X04031 |
| SMU / Hours | 99 |
| Location | Henderson, NV 89052, United States |



FEATURES

General

- Air Conditioner
- Differential Lock
- Front Auxiliary Hydraulics
- Lighting
- Radio - AM FM Radio
- Ride Control
- Steering - 2 Wheel
- Air Suspension Seat
- Drive - 4 Wheel
- Front Coupler *Hydraulic*
- Pattern Changer
- Rear Auxiliary Hydraulics
- ROPS
- Stick - Extended
- Controls, Joystick
- Engine Enclosures
- Integrated Toolcarrier
- Product Link
- Rear Coupler *MANUAL*
- STABILIZER GUARDS

Regulatory

- Emissions Level - EPA - EPA **TIER 4f**
- Ultra Low Sulfur Diesel Fuel

Attachments

- Bucket
Front- 95" -1.50 CYD Rear- 36"
- Forks
54" pallet forks

NOTES

Lease return

CONDITION

●●● Good

●● Fair

● Poor

GENERAL APPEARANCE

Battery Compartment



Bottom Guards



Cab or Canopy



Counterweight



DEF Tank



Drive Shaft Guard



One bent cross bar.

Engine Hood



Engine Enclosure Panels



Fenders



Fuel Tank



Grab Handles



Guarding Panels



Dents/ damage to bottom of fuel tank guard plate.

Main Frames



Paint & Decals



Plastic Covers



Radiator Enclosure / Grill



Sheet Metal Panels



Stabilizer Frames



Minor dent in right outrigger cylinder guard.

Steps / Ladder



Storage Compartments



Cleaning Required

NO

S.O.S. Taken

YES

Engine, Transmission, Hydraulic

Service Required?

NO

SAFETY ITEMS

Alternate Exit



Back-Up Alarm



Horn



Implement Safety Lockout



Lift Arm Safety Brace



Rear View Mirrors



Reflectors / Reflective Labels



Seat-Belt



Warning / Safety Labels



ROPS

YES

ROPS Certification Label

YES

OPERATOR STATION

Air Conditioner



Cab Floor



Cab Interior Trim



Cooled to 49 degrees at 85 ambient temp.

Cab Storage Compartments



Controls-Throttle



Dash Console



Doors / Latches



Gauges



Gauges / Instrument Panel



Glass & Windows



Heater



Hour Meter



HVAC System



Interior Lights



Joystick Console



Monitor / Warning Alarm



Seat / Suspension / Arm Rests



Steering Column Tilt



Switches



Windshield Wipers



ECM Downloaded

YES

No active or logged fault codes.

O&M Manual

YES

Radio

YES

Safety Manual

YES

ENGINE

| | | |
|--|---|---|
| Belts & Pulleys  | Engine Air Cleaner  | Engine Air Inlet  |
| Engine Block / Cylinder Head  | Engine Exhaust  | Engine Front / Rear Housings  |
| Engine Mounts / Supports  | Engine Operating Condition  | Fuel Lines & Filters  |
| Governor Control  | Turbo  | |
| Emission Label YES | Engine Blow-By? NO | Engine Noises? NO |
| Engine Oil Leaks NO | Fluid Levels OK? YES | Water In Engine Oil? NO |
| Anti-Freeze Color Red | Engine Oil Pressure Normal | Engine Smoke Color Normal |

COOLING SYSTEM

| | | |
|--|---|--|
| Coolers  | Engine Cooling Tubes & Hoses  | Fan Drive  |
| Radiator  | Radiator Fan  | Radiator Shroud / Fan Guard  |
| Water Pump  | | |
| Compression In Radiator? NO | Cooling System Leaks NO | |

ELECTRICAL, STARTING AND CHARGING SYSTEM

| | | |
|--|---|--|
| Alternator Motor  | Battery & Wiring  | Starter Motor  |
|--|---|--|

Wiring Harness



Work Lights / Lighting



Engine Block Heater

YES

Ether Starting Aid

YES

No bottle



Rotating Beacon

NO

TRANSMISSION

4-Wheel Drive Operating Condition



Case-Transmission



Controls-Transmission



Torque Converter



Transmission Oil Lines & Tubes



Transmission Operating Condition



Transmission - Noisy

NO

Transmission Oil Leaks

NO

STEERING

Controls-Steering



Steering Operating Condition



Steering Cylinder



Steering Linkage



Steering Oil Lines & Tubes



Steering Valves / Pumps



Tie Rods / Rod Ends



BRAKE

Brakes Oil Lines & Tubes



Brakes Operating Condition



Control-Service Brake



Park Brake Holding Ability Test



Held 3rd gear to full throttle.

Parking Brake



Pedal



Brake System Leaks NO

Holding What Gear?
Service brakes held 1st gear to full throttle.

HYDRAULICS

Boom Lift Cylinders


Boom Swing Cylinders


Bucket & Hoist Kickout


Controls-Hydraulic


Cylinder Pins & Bushings


Extendable Stick Cylinder


Front Tilt Cylinders


Hydraulic Oil Lines & Tubes


Hydraulic Operating Condition


Lift Cylinders


Pattern Changer Operating Condition


Pumps & Valves


Rear Tilt Cylinder


Ride Control Operation


Stabilizer Cylinders


Stick Cylinder


Tank Hydraulic


Hydraulic System Leaks
NO

BOOM & STICK

Boom


Boom Pins & Bushings


Extendable Stick


Extendable Stick Lock


Stick


Stick Pins & Bushings


Swing Frame


Swing Frame Pins & Bushings


Swing Lock


FRONT BUCKET

Bucket Bottom


Bucket Floor


Bucket Sides


Bucket Pins & Bushings


Cutting Edges


Lift & Tilt Kickouts


Loader Frame


Loader Frame Pins & Bushings


Tilt Linkages


Tilt Linkages Pins & Bushings


Front Bucket Quick Coupler
YES
Hydraulic

Bucket Capacity
95 in / 1.50 CYD

REAR BUCKET

Bucket Bottom


Bucket Mounts


Bucket Sides


Bucket Teeth / Adapters


Coupler Pins & Bushings


Rear Bucket Pins & Bushings


Rear Tilt Linkages


Coupler Quick Disconnect
YES

Bucket Width
36 in

ATTACHMENTS / WORK TOOLS

Overall Operating Condition - ATTACHMENTS / WORK TOOLS



Fork
YES
54" pallet forks



FINAL DRIVES

Axle Housings

Differential / Axle Mounts

Differential Lock Control

Differentials

Drive Shafts

Front Final Drives

Rear Final Drives

Axles, Differentials, Finals-Leaks
NO

TIRES

| | Make / Serial# | Tread Depth in 1/32" | % Life Remaining | Recapped | Tread Cuts/Chunks | Side Cuts Section |
|-------------|----------------|-------------------------|---------------------|-----------|----------------------|----------------------|
| Left Front | Goodyear SGL | 28 | 90 | NO | YES | NO |
| Left Rear | Goodyear IT525 | 28 | 82 | NO | YES | NO |
| Right Front | Goodyear SGL | 28 | 90 | NO | YES | NO |
| Right Rear | Goodyear IT525 | 28 | 82 | NO | YES | NO |

Rims / Wheels Condition

Front Tire Size
12.5/80-18

Rear Tire Size
19.5L-24

COMMENTS, MISC. REPAIRS, GENERAL REMARKS

Date of Machine Inspection  50

Inspected 10/6/2025 with 99
hours.

MARKETING PHOTOS (16)





