

2019 CAT 73004 ARTICULATED TRUCKS

INSPECTION DETAILS

Inspection Type	Trade
Inspection Form	Standard
Inspection #	10255820
Inspection Status	Completed
Created	12/05/25 14:46:31
Updated	12/11/25 08:05:11
Created By	Calderas, Marco
Inspector	Calderas, Marco
Reviewers	Calderas, Marco
Salesperson	Schultis, Derrick R.
Serial #	3T300505
SMU / Hours	4,942
Location	Eloy, AZ, United States



FEATURES

General

- Air Conditioner
- Canopy
- Mirrors
- Rear View Camera
- Air Suspension Seat
- Lighting
- Product Link
- ROPS - Enclosed
- Auto Lube
- Lube Truck
- Radio - AM FM Radio
- Water Truck

Regulatory

- Emissions Level - EPA - EPA
TIER 4f
- Ultra Low Sulfur Diesel Fuel

CONDITION

●●● Good

●● Fair

● Poor

Approved Repair

GENERAL CONDITIONBody
●●●Frame
●●●General
●●●ET Product Status Report
Download
YESLogged / Active Codes
YESMachine Starts and is Operable
YESS.O.S. (All Compartments)
YES
Engine, hydraulics and transmission.Tires are Aired Up and Drivable
YESVisible Oil Leaks
NO**GENERAL APPEARANCE**Battery Box
●●●Bumper
●●●Cab or Canopy
●●●Crankcase Guard / Transmission
Guard
●●●Decals
●●●Fenders
●●

●4

Right side fender has cracks And
guard-muds on left and right are cut.Front Frame Welds
●●●Fuel Tank
●

●1

Fuel level sensor bad. (fuel tank at
100%)Grab Irons
●●●Hood / Actuator
●●

●1

Paint
●●●Plastic (Exterior)
●●

●2

HOOD & DOOR GP -HOOD Left side
hood panel is bentPANEL GP-CAB right side panel
crackedRadiator Grill
●●●Rear Frame Welds
●●●Sheet Metal
●●●

Steps / Ladder



WALKWAY GP



WALKWAY GP Left side walk way platform has rust.



Cleaning Required

YES

SAFETY ITEMS

Back Up Alarm



Camera(s)



Horn



Safety Locks / Pins



Seat Belt / Date Driver



Out dated 02/19 driver seat belt

Seat Belt / Date Passenger



Outdated 02/19 passenger seat belt

Parking Brake Functioning

YES

ROPS

YES

ROPS Certification Plate

YES

Safety Decals In Place

YES

Safety Decals Legible

YES



Service Brakes Functioning

YES

Notes - SAFETY ITEMS

Machine has a GARMIN GPS ready.

OPERATOR STATION

Air Conditioner



Armrrests



Driver seat arm rest both left and right are broken

Cab Filter / Heat Vent Louvres



Dash Console



Door Latches / Hinges / Seals



Floor Boards / Mats



Gauges



Glass



Headliner



Heater / Defroster



Hour Meter - GAUGES,
OPERATION STATION, CONSOLE



Interior Lights



Interior Plastic / Fabric



Mirrors



Monitoring Display



Pans/Guards



Radio



Seat Cushions / Suspension /



Type



Seat recliner does not work Driver seat arm rest both left and right are broken (I tested the seat recliner and is working perfectly fine)

Switches



Transmission Controls



Visor / Sunshade



Windows



Windshield Wipers



Sprayers do not work (wiper nozzle sprayer is plugged)

Current O&MM

NO

Current Parts Manual

NO

Current Safety Manual

NO

ENGINE

Belts / Pulleys - ENGINE



Serpentine belt has cracks



Engine Oil Level / Condition



Engine Supports / Mounts



Exhaust / Muffler / Stack



Fuel Injection System



Governor



Intake / Air Filters



Part of service



Operating Condition - ENGINE



Turbocharger / Blower



Blow By

NO

Emissions Decal Legible

YES

Fuel Leaks

NO

Knocking
NO

Oil Leaks
NO

Pre Lube System
YES

4

Auto lube lines are disconnected
and grease valve is rusty along
with all fittings and lines

Service Needed
YES

Water in Oil
NO

Oil Pressure (H/L/N)
Normal

Smoke Color (B/D/L/W)
Normal

EMISSIONS

Aftertreatment Heat Shields /
Guards


Diesel Exhaust Fluid (DEF) Tank


Diesel Particulate Filter (DPF)
Condition / Service Hours


Aftertreatment System Codes
YES

Leaks / Type
NO

COOLING SYSTEM

Anti-Freeze Level / Color /
Condition

Red

Coolers


Fan


Fan Drive / Type


Fan Shrouds / Guards


GUARD GP-RADIATOR -RH

GUARD GP-RADIATOR -RH Is broken
on 2 Different parts and right side grill
is bent. (Its been repair before)

Hoses & Tubes


Radiator


Water Pump


Compression in Radiator
NO

Coolant Leaks
NO

Oil in Anti-Freeze
NO

Standard Radiator
YES

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator



Batteries / Cables / Master

Disconnect



Starter



Wiring



Work Lights



Active Codes

NO

Block Heater

NO

Ether Aid

NO

Jump Start Terminal

YES



Signal Lights

YES

TRANSMISSION

Case



Controls



Cooler



Lines / Fittings - TRANSMISSION



Overall Operating Condition -
TRANSMISSION



Pump - TRANSMISSION



Retarder



Temp / Pressure Gauges



Torque Converter



Transmission - Forward Shifts



Transmission - Reverse Shifts



Valves



Auto Shift

YES

Leaks - TRANSMISSION

NO

Transmission - Noisy

NO

STEERING

Articulation P&B



Hand Metering Unit



Lines / Fittings - STEERING



Oscillation Hitch



Overall Operating Condition



Steering Column / Tilt



Steering Cylinder


Steering Linkage


Steering Pump


Wheel


SUSPENSION

Center A-Frame


Center Bearings


Center Rubber Springs


Center Torsion Bars


Front A-Frame


Front Bearings


Front Rubber Springs


Front Torsion Bars


Left Suspension Beam


Rear A-Frame


Rear Bearings


Rear Rubber Springs


Rear Torsion Bars


Right Suspension Beam


BRAKE

Accumulators - BRAKE


Brake Drums / Rotors


Brake Guards


Compressor


Control Valve


Hydraulic Cooler


Lines


Parking Brake Operation


Pedal


Pump - BRAKE


Service Brake Operation


Type (Wet, Dry)


Leaks - BRAKE
NO

HYDRAULICS

Hydraulic Valves



Pump



Tank / Sight Glass / Cap



Leaks - HYDRAULICS

NO

FINAL DRIVES

Center Axle



Center Final Drives



Drive Shaft



Front Axle - FINAL DRIVES



Front Final Drives



Rear Axle



Rear Final Drives



Transfer Case / Dropbox



Universal Joints



Wheel Lugs & Rims



TIRES

	Make / Serial#	Tread Depth in 1/32"	% Life Remaining	Recapped	Tread Cuts/Chunks	Side Cuts Section
Left Center	Bridgestone	34 32/nds	75.56%	NO	YES	YES
Left Front	Bridgestone	41 32/nds	91.11%	NO	YES	YES
Left Rear	Bridgestone	34 32/nds	75.56%	NO	YES	YES
Right Center	Bridgestone	36 32/nds	80.00%	NO	YES	YES
Right Front	Bridgestone	41 32/nds	91.11%	NO	YES	YES
Right Rear	Boto	37 32/nds	82.22%	NO	YES	YES

Radial
YES

Average Life Remaining - TIRES
82.59

Notes - TIRES
Several tires have large cuts

 3 Tire Size - TIRES
23.5R25


COMMENTS, MISC. REPAIRS, GENERAL REMARKS


comment 1
Inspection

comment 2
PM-Service (please perform a
PM4)


MARKETING PHOTOS (31)













LINE ITEM PHOTOS (54)

Logged / Active Codes

YES


Code	Description	Occ.	First	Last
96-3	Fuel Level Sensor : Voltage Above Normal	22	4920	4942

Logged Event Codes [Total Operating Hours = 4943 hours] - Transmission 730 (S7M00807)

Fenders



Right side fender has cracks
And guard-muds on left and
right are cut.



Fuel Tank

●
Fuel level sensor bad. (fuel tank
at 100%)



Hood / Actuator

●●
HOOD & DOOR GP -HOOD Left
side hood panel is bent



Plastic (Exterior)

●●
PANEL GP-CAB right side panel
cracked



WALKWAY GP



WALKWAY GP Left side walk way platform has rust.



Camera(s)



Seat Belt / Date Driver



Out dated 02/19 driver seat belt



Seat Belt / Date Passenger

●
Outdated 02/19 passenger seat belt



Safety Decals Legible

YES





Air Conditioner

●●●



Armrests

Driver seat arm rest both left and right are broken



Heater / Defroster



Radio



Seat Cushions / Suspension /

Type



Seat recliner does not work
Driver seat arm rest both left
and right are broken (I tested
the seat recliner and is working
perfectly fine)



Windshield Wipers



Sprayers do not work (wiper
nozzle sprayer is plugged)



Belts / Pulleys - ENGINE



Serpentine belt has cracks



Intake / Air Filters





Part of service



Pre Lube System

YES


Auto lube lines are disconnected and grease valve is rusty along with all fittings and lines



GUARD GP-RADIATOR -RH



GUARD GP-RADIATOR -RH Is broken on 2 Different parts and right side grill is bent. (Its been repair before)



Jump Start Terminal
YES



Make / Serial#	Tread Depth in 1/32"	% Life Remaining	Recapped	Tread Cuts/Chunks	Side Cuts Section
Left Center	Bridgestone	34 32/nds	75.56%	NO	YES
					
Left Front	Bridgestone	41 32/nds	91.11%	NO	YES
					



Make / Serial#	Tread Depth in 1/32"	% Life Remaining	Recapped	Tread Cuts/Chunks	Side Cuts Section	
Left Rear	Bridgestone	34 32/nds	75.56%	NO	YES	YES



Make / Serial#	Tread Depth in 1/32"	% Life Remaining	Recapped	Tread Cuts/Chunks	Side Cuts Section
Right Center	Bridgestone	36 32/nds	80.00%	NO	YES
					
					
Make / Serial#	Tread Depth in 1/32"	% Life Remaining	Recapped	Tread Cuts/Chunks	Side Cuts Section
Right Front	Bridgestone	41 32/nds	91.11%	NO	YES
					



Make / Serial#	Tread Depth in 1/32"	% Life Remaining	Recapped	Tread Cuts/Chunks	Side Cuts Section
Right Rear Boto	37 32/nds	82.22%	NO	YES	YES



Notes - TIRES

Several tires have large cuts

