



2015 CAT  
262D  
SKID STEER LOADERS

INSPECTION DETAILS

Inspection Type	Consignment
Inspection Form	Skid Steers
Inspection #	10256623
Inspection Status	Inspected
Created	12/10/25 07:20:45
Updated	12/10/25 07:53:39
Created By	Earl, Ryan
Inspector	Earl, Ryan
Engine Serial #	8FA4774
Last Preventative Maintenance	Sep 02, 2022
Serial #	DTB03027
SMU / Hours	4,407
Location	APACHE JUNCTION, AZ, United States



FEATURES

General

- Anti-theft System
- Auxiliary Hydraulics Flow - Standard Flow
- Coupler Type - Mechanical
- Lighting
- ROPS - Open
- Self Leveling

Regulatory

- Emissions Level - EPA - Tier4
- Emissions Level - EU - Stage3b
- Emissions Level - Japan - 2013 Regulation
- Emissions Level - Switzerland - Switzerland

Attachments

- Bucket  
78 IN / .62 CYD GP

NOTES

INSPECTION FOR CONSIGNMENT.

## CONDITION



Good



Fair



Poor

Approved Repair

## GENERAL APPEARANCE

Body Frame



Bumper



Cab or Canopy



Engine Access Door



ENGINE DOOR MESH SCREEN DENTED AND TORN.



2

Fuel Tank



Grab Irons



Paint & Decals



PAINT IS FADED AND OXIDIZED, DECALS ARE WEATHERED AND SCRATCHED.



2

Radiator Grill & Shroud



GRILL SPRING BLOWN.



1

Sheet Metal



BOTTOM ENGINE ACCESS PANEL MISSING.



1

Steps / Ladder



STEPS LIGHTLY BENT.



1

Cleaning Required

**YES**

WASH FOR TRANSPORT AND DELIVERY.

S.O.S. Taken

**YES**

ENG HYD

Service Required?

**YES**

NEEDS 500 HOUR PM SERVICE.

## SAFETY ITEMS

Back-Up Alarm



Horn



Lift Arm Safety Brace



Parking Brake



Rear View Mirrors



Reflectors / Reflective Labels



Seat-Belt



OUT OF COMPLIANCE, INSTALLED MARCH 2015.



1

Warning / Safety Labels



ROPS  
**YES**

ROPS Certification Label  
**YES**

## OPERATOR STATION

Cab Interior Trim  
●●●

Dash Console  
●●●

EMS Panel / Warnings  
●●●

Floor Boards  
●●  
FLOORMAT MISSING.



Gauges  
●●●

Glass & Windows  
●●  
CANOPY ROOF WINDOW MISSING.



Interior Lights  
●●●

Joystick Console  
●●  
LEFT OPERATOR CONSOLE CRACKED  
AND RIGHT OPERATOR CONSOLE  
CHIPPED, JOYSTICK GRIPS ARE STICKY.



Meter  
●●●

Seat / Suspension / Arm Rests  
●  
SEAT CUSHIONS SPLIT, ARMRESTS  
LOOSE, AND SEAT SUSPENSION  
FRAME LOOSE.



Switches  
●●●

Current O&MM  
**NO**  
NEEDS BOOKS.

Current Safety Manual  
**NO**

ECM Downloaded  
**YES**

## ENGINE

Air Cleaners  
●●  
DUST VALVE MISSING, NEEDS  
SERVICED.



Belts & Pulleys  
●●  
BELT WORN AND NOISY.

Engine Block / Cylinder Head  
●●  
INJECTOR CYLINDER SEEPING ON  
VALVE COVER.



Engine Operating Condition  
●●●

Engine Supports  
●●●

Exhaust / Muffler  
●●●

Fuel Lines & Filters  
●●●

Governor  
●●●

Turbocharger / Blower  
●●●

Emission Label  
**YES**

Engine Oil Leaks  
**NO**

Fluid Levels OK?  
**NO**  
ANTI-FREEZE BOTTLE EMPTY.



Oil Pressure (H/L/N)  
NORMAL

Smoke (B/D/L/W)  
CLEAR

COOLING SYSTEM

Engine Cooling Tubes & Hoses  
●●●

Fan  
●●●

📷1 Fan Drive  
●●●

Radiator  
●●  
RADIATOR NEEDS COMBED AND  
WASHED OUT.

📷1 Water Pump  
●●●

Cooling System Leaks  
**YES**  
ANTI-FREEZE BOTTLE CRACKED.

📷1

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator  
●●●

Batteries / Cables  
●●●

Battery Compartment  
●●●

Lighting  
●●●  
FRONT LIGHTS REPLACED WITH  
AFTERMARKET RIGID LED LIGHTS.

📷3 Starter  
●●●

Wiring  
●●●

HYDRAULICS

Controls-Hydraulic  
●●●

Controls-Travel & Steering  
●●●

Hydraulic Oil Lines & Tubes  
●●  
HOSE CLAMP SEEPS FROM PUMP LINE.

📷1

Hydraulic Operating Condition  
●●●  
NO OPERATIONAL ISSUES OBSERVED  
AT TIME OF INSPECTION.

Lift Cylinders  
●●●

Pumps & Valves  
●●●

Self Leveling  
●●●

Tank Hydraulic  
●●●

Tilt Cylinder  
●●  
TILT CYLINDER BUSHINGS HAVE  
MOVEMENT AND WEAR.

📷2

Hydraulic System Leaks

YES

LEFT DRIVE MOTOR SEEPING.

📷1

BUCKET

Bucket Floor		Bucket Bottom		Bucket Sides			
●●●		●●●		●●●			
Coupler Pins & Bushings	📷2	Cutting Edges	📷1	Loader Frame			
●●		●		●●●			
COUPLER PINS AND BUSHINGS HAVE MOVEMENT.		EDGE AND HARDWARE MISSING.					
Loader Pins & Bushings	📷4						
●●							
LOADER ARM PINS AND BUSHINGS HAVE MOVEMENT.							
Coupler Quick Disconnect							
YES							
Bucket Capacity		Bucket S/N	📷1				
.62 CYD		A416BBK20145					

TIRES


	Make / Serial#	Tread Depth in 1/32"	% Life Remaining	Recapped	Tread Cuts/Chunks	Side Cuts Section
Left Front	SAMSON PREMIUM SKID STEER	6	26		YES	
Left Rear	SAMSON PREMIUM SKID STEER	13	57		YES	
Right Front	SAMSON PREMIUM SKID STEER	10	43		YES	

Right Rear	SAMSON PREMIUM SKID STEER	10	43	YES
------------	---------------------------------	----	----	-----

---

Rims / Wheels Condition



Axles, Differentials, Finals-Leaks 1

YES

LEFT DRIVE MOTOR SEEPS.

Notes - TIRES	Tire Size - TIRES
ROUGHLY 42.39% WEAR LIFE LEFT.	12-16.5

---

COMMENTS, MISC. REPAIRS, GENERAL REMARKS

comment 1  
INSPECTED 12/8/2025

MARKETING PHOTOS (23)







