


# Off Highway Trucks Inspection Report

Inspection Date: 9/5/2025

| MACHINE DETAILS   |   |   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
|---|---|---|---|---|---|---|--|---|---|---|---|---|---|---|---|---|---|--|---|---|---|
| Manufacturer:KO   | Model:HD785-7   | S/N:KMTHD023C26007166   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| Year:2007   | Eng S/N:N/A   | Trans S/N:N/A   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| SMU/Hrs:45611   | Hours Date:7/25/2025  |   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| Last Schedule:  | Last CTS:   | Last PM:9/25/2025   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| Date Oil Sample Sent to Lab:7/25/2025   | Oil Sample:Attached   |   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| Recommendations:  |   |   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| OFF HIGHWAY TRUCK CONFIGURATION   |   |   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| Machine rebuild: No   | Rebuild type: Work Ready  | Machine rebuild hours:  |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| Air Conditioner: Yes  | Body Liner: Yes   | Heated Bed: Yes   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| Tail Gate: No   | Side Boards: No   | Auto Traction Cont: No  |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| Retarder: No  | Fast Fuel: Yes  | Hi Speed Oil Change: No   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| Engine Tier Rating: TIER 2  | Tire Size: 27.00R49   | Product Link: No  |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| Anti-Theft System: No   | Comments:   | Bed Configuration: END DUMP   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| ECM Download: NA  | Articulated Truck: No   | Non Articulated Truck: Yes  |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| Product Link: Inquire for options on  |   |   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| GENERAL APPEARANCE  |   |   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| CODE  | REMARKS   |   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| Radiator Grill & Shroud   | Good  |   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| Engine Enclosure  | Good  |   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| Hood / Stack  | Good  |   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| Fenders   | Good  |   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| Fuel Tank   | Good  |   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| Crankcase Guard   | Good  |   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| Battery Box   | Good  |   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| Main Frame Welds  | Good  |   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| Diff Supports   | Good  |   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| Bumper  | Good  |   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| Counterweight   | Good  |   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| Pre-Cleaner Bowl  | Good  |   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| Cab   | Good  |   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| Steps / Ladder  | Good  |   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| Grab Irons  | Good  |   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| Paint   | Good  | Repainted in July 2025  |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| Engine Doors  | Good  |   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| Sheet Metal   | Good  |   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| Car Body  | Good  |   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| SOS Taken   | Yes   | Attached  |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| Cleaning Required   | No  | Truck is clean  |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| Notes   | Complete and operational.   |   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
|  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |
| SAFETY ITEMS  |   |   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| CODE  | REMARKS   |   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| Safety Decals In Place  | Yes   |   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| Safety Decals Legible   | Yes   |   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| Articulation Safety Bar & Pins  | Good  |   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| Horn  | Good  |   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| Parking Brake   | Good  |   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| ROPS  | Yes   |   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| Notes   | Complete and operational.   |   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
|  |   |   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| GAUGES, OPERATOR STATION, CONSOLE   |   |   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |
| CODE  | REMARKS   |   |   |   |   |   |  |   |   |   |   |   |   |   |   |   |   |  |   |   |   |

# Off Highway Trucks Inspection Report

|                           |                           |  |
|---------------------------|---------------------------|--|
| Dash Console              | Good                      |  |
| Hour Meter                | Good                      |  |
| Gauges                    | Good                      |  |
| Switches                  | Good                      |  |
| Wipers                    | Good                      |  |
| Air Conditioner           | Good                      | A/C is cooling properly with air directors replaced as needed. |
| Heater                    | Good                      |  |
| Interior Lights           | Good                      |  |
| Seat Cushions / Arm Rests | Good                      | Operators seat and suspension replaced with new OEM            |
| Floor Boards              | Good                      |  |
| EMS Panel / Warnings      | Good                      |  |
| Doors                     | Good                      |  |
| Door Latches              | Good                      |  |
| Glass / Mirrors           | Good                      | Damaged glass replaced. New mirrors stored in the cab.         |
| Bed Control               | Good                      |  |
| Seat Belt                 | Good                      | Operators seat belts replaced with new OEM                     |
| Parts Book                | No                        |  |
| Safety Manual             | No                        |  |
| O&MM                      | No                        |  |
| Back-up Alarm             | Yes                       |  |
| ROPS Cert Plate           | Yes                       |  |
| Notes                     | Complete and operational. |  |



## ENGINE

|                            | CODE                      | REMARKS |
|----------------------------|---------------------------|---------|
| Oil Leaks                  | No                        |         |
| Blow By                    | No                        |         |
| Knocking                   | No                        |         |
| Compression In Radiator    | No                        |         |
| Water In Oil               | No                        |         |
| Fluid Levels OK?           | Yes                       |         |
| EPA Decal                  | No                        |         |
| Anti-freeze Color          | Red                       |         |
| Oil Pressure (H/L/W)       | Normal                    |         |
| Smoke (B/D/L/W)            | Normal                    |         |
| Operating Condition        | Good                      |         |
| Turbocharger / Blower      | Good                      |         |
| Fuel Injection System      | Good                      |         |
| Governor                   | Good                      |         |
| Engine Supports            | Good                      |         |
| Air Cleaners               | Good                      |         |
| Exhaust / Muffler          | Good                      |         |
| Belts / Pulleys            | Good                      |         |
| Engine Brake               | Good                      |         |
| Oil Filter Condition (Cut) | Good                      |         |
| Notes                      | Complete and operational. |         |



## COOLING SYSTEM

|            | CODE                      | REMARKS |
|------------|---------------------------|---------|
| Radiator   | Good                      |         |
| Coolers    | Good                      |         |
| Hoses      | Good                      |         |
| Water Pump | Good                      |         |
| Fan        | Good                      |         |
| Fan Drive  | Good                      |         |
| Leaks      | No                        |         |
| Notes      | Complete and operational. |         |

# Off Highway Trucks Inspection Report



## ELECTRICAL, STARTING AND CHARGING SYSTEM

| CODE               | REMARKS                   |
|--------------------|---------------------------|
| Batteries / Cables | Good                      |
| Starter            | Good                      |
| Alternator         | Good                      |
| Wiring             | Good                      |
| Pre-Heater         | Good                      |
| Lighting           | Good                      |
| Ether Aid          | No                        |
| Block Heater       | No                        |
| Notes              | Complete and operational. |




## TRANSMISSION

| CODE                          | REMARKS                   |
|-------------------------------|---------------------------|
| Transmission - Type           | PS                        |
| Case                          | Good                      |
| Controls                      | Good                      |
| Seals                         | Good                      |
| Torque Converter              | Good                      |
| Universal Joints              | Good                      |
| Temp / Pressure Gauges        | Good                      |
| Lines / Fittings              | Good                      |
| Transmission - Forward Shifts | Good                      |
| Transmission - Reverse Shifts | Good                      |
| Pump                          | Good                      |
| Cooler                        | Good                      |
| Drive Shaft                   | Good                      |
| Retarder                      | Good                      |
| Oil Filter Condition          | Good                      |
| (Cut)                         | No                        |
| Operating Condition           | Good                      |
| Transmission - Noisy          | No                        |
| Leaks                         | No                        |
| Notes                         | Complete and operational. |



## STEERING


| CODE                         | REMARKS                                    |
|------------------------------|--|
| Front Axle                   | Good                                       |
| Steering Linkage             | Good                                       |
| Steering Gear Box            | Not Applicable                             |
| Tie Rods / Rod Ends          | Good                                       |
| Steering Valves / Pumps      | Good                                       |
| Steering Cylinder            | Good                                       |
| Steering Tank                | Steering cylinders reconditioned June 2025 |
| Pivot Pins & Bushings        | Good                                       |
| Articulation Pins & Bushings | Not Applicable                             |
| Suspension Cylinders         | Good                                       |
| Notes                        | Complete and operational.                  |
| Torsion Rods                 | Good                                       |
| Trunnions                    | Good                                       |



## BRAKES

# Off Highway Trucks Inspection Report

| CODE                        | REMARKS  |
|-----------------------------|--|
| Type (Pedal / Lever)        | Pedal  |
| Type (Wet, Dry)             | Wet  |
| Drums / Rotors              |  |
| Control Valve               | Good   |
| Pump                        | Good   |
| Lines                       | Good   |
| Master Cylinder             | Good   |
| Compressor                  | Not Applicable   |
| Brake Linkage               | Good   |
| Accumulators                | Good   |
| Parking Brake               | Good   |
| Brakes Holding In What Gear | All  |
| Notes                       | Complete and operational with normal wear for the age and hours. |



## FINAL DRIVES

| CODE                | REMARKS                   |
|---------------------|---------------------------|
| Wheel Lugs & Rims   | Good                      |
| Rear Final Drives   | Good                      |
| Rear Axle           | Good                      |
| Differential        | Good                      |
| Torsion Rods        | Good                      |
| Trunnion / Wishbone | Good                      |
| Leaks               | No                        |
| Notes               | Complete and operational. |



## HYDRAULICS

| CODE                   | REMARKS                   |
|------------------------|---------------------------|
| Suspension Cylinders   | Good                      |
| Operating Condition    | Good                      |
| Tank                   | Good                      |
| Lift Cylinders         | Good                      |
| Hose Lines             | Good                      |
| Pumps & Valves         | Good                      |
| Control Linkage        | Good                      |
| Filter Condition (Cut) | Good                      |
| Leaks                  | No                        |
| Notes                  | Complete and operational. |



## TRUCK BODY

| CODE                      | REMARKS                                    |
|---------------------------|--|
| Bed Liner                 | Good                                       |
|                           | Rear liner worn at rear edge, operational. |
| Sides & Side Boards       | Good                                       |
| Ribs & Stringers          | Good                                       |
| Hinge Pins & Brackets     | Good                                       |
| Overhang                  | Good                                       |
| Bottom                    | Good                                       |
| Pads                      | Good                                       |
| Safety Pins               | Good                                       |
| Tailgate                  | Not Applicable                             |
| Rock Knockers / Mud Flaps | Good                                       |
| Heated Body               | Yes  |
| Notes                     | Complete and operational.                  |

# Off Highway Trucks Inspection Report



## TIRES

|                   | MAKE S/N                       | TREAD DEPTH<br>1/32" | % LIFE LEFT | RECAPPED | TREAD<br>CUT/CHUNKS | SIDE CUTS<br>SECTIONS |
|-------------------|--------------------------------|----------------------|-------------|----------|---------------------|-----------------------|
| Right Front       | Maxam MS412<br>47021SF12304    | 83.00                | 100.00      | No       | No                  | No                    |
| Right Center      |                                | 0.00                 | 0.00        |          |                     |                       |
| Right Rear Outer  | Maxam MS412<br>44117SE10824    | 83.00                | 100.00      | No       | No                  | No                    |
| Right Rear Inside | Maxam MS412<br>44137SE20829    | 83.00                | 100.00      | No       | No                  | No                    |
| Left Rear Outer   | Maxam MS412<br>44127SE20827    | 83.00                | 100.00      | No       | No                  | No                    |
| Left Rear Inside  | Maxam MS412<br>44137SE30828    | 83.00                | 100.00      | No       | No                  | No                    |
| Left Center       |                                | 0.00                 | 0.00        |          |                     |                       |
| Left Front        | Maxam MS412<br>47031SF22307    | 83.00                | 100.00      | No       | No                  | No                    |
| Tire Size         | 27.00R49 E-4                   |                      |             |          |                     |                       |
| Average Life Left | 100                            |                      |             |          |                     |                       |
| Spare             | No                             |                      |             |          |                     |                       |
| Notes             | ALL TIRES ARE IN NEW CONDITION |                      |             |          |                     |                       |
| Tires Needed      |                                |                      |             |          |                     |                       |




## SERVICE

| CODE           | REMARKS  |
|----------------|--|
| Service Needed | Current with PM4 service. All fluids and filters changed |
|                |  |
|                |  |

## GENERAL REPAIRS AND REMARKS

Repairs Needed: A/C repairs completed and function properly.  
 General comments: All fluids and filters changed PM4 All engine exhaust leaks repaired. Tires in new and unused condition. Batteries recently serviced and operational.  
 The truck was repainted in July 2025 and in good condition.



# Off Highway Trucks Inspection Report

