

2022 CAT 259D3 COMPACT TRACK LOADER

INSPECTION DETAILS

Inspection Type	Marketing
Inspection Form	MULTI-TERRAIN LOADER
Inspection #	10269729
Inspection Status	Created
Created	02/10/26 10:35:49
Updated	02/10/26 10:39:38
Created By	Fuller, Scott U.
Inspector	Heath, Jason
Salesperson	Heath, Jason
Stock #	E196744
Serial #	CW920971
SMU / Hours	41
Location	Henderson, NV 89015, United States



FEATURES

General

- **2 SPEED TRAVEL**
- **AUXILIARY HYDRAULICS**
- **EPA LABEL**
- **HIGH FLOW HYDRAULICS**
- **PRODUCT LINK**
- **ULTRA LOW SULFUR DIESEL FUEL**
- **AIR CONDITIONER**
- **COUPLER, HYDRAULIC**
- **EROPS**
- **LIGHTING**
- **RIDE CONTROL**
- **AM FM RADIO**
- **DISPLAY,LCD CAMERA**
- **HEATER / DEFROSTER**
- **PILOT CONTROL**
- **SELF LEVELING**

CONDITION

●●● Good

●● Fair

● Poor

GENERAL APPEARANCE

Body Frame



Bumper



Cab or Canopy



Counterweight



Engine Access Door



Fuel Tank



Grab Irons



Paint & Decals



Plastic



Radiator Grill & Shroud



Sheet Metal



Steps / Ladder



Cleaning Required

NO

S.O.S. Taken

NO

Service Required?

NO

Hydraulic and Engine samples
taken during previous inspection
at 39 hrs. Results Good

SAFETY ITEMS

Alternate Exit



Back-Up Alarm



Horn



Lift Arm Safety Brace



Parking Brake



Rear View Mirrors



reflectors



Reflectors / Reflective Labels



Seat-Belt



Warning / Safety Labels



ROPS

YES

ROPS Certification Label

YES

GAUGES, OPERATOR STATION, CONSOLE

Air Conditioner 	Cab Interior Trim 	Dash Console 
Doors / Latches 	EMS Panel / Warnings 	Floor Boards 
Gauges 	Glass & Windows 	Headliner 
Heater 	Interior Lights 	INterior trim 
Joystick Console 	Meter 	Seat / Suspension / Arm Rests 
Switches 	Windshield Wipers 	
Camera? YES	Cameras YES	Current O&MM YES
Current Safety Manual YES	ECM Downloaded YES No active or logged fault codes.	Radio YES AM/FM Radio

ENGINE

Air Cleaners 	Belts & Pulleys 	Engine Block / Cylinder Head 
Engine Operating Condition 	Engine Supports 	Exhaust / Muffler 
Fuel Lines & Filters 	Governor 	Turbocharger / Blower 
Blow By NO	Compression in Radiator NO	Emission Label YES

Engine Oil Leaks
NO

Fluid Levels OK?
YES

Knocking
NO

Water in Oil
NO

Anti-Freeze Color
Red

Oil Pressure (H/L/N)
Normal

Smoke (B/D/L/W)
Clear

COOLING SYSTEM

Coolers


Engine Cooling Tubes & Hoses


Fan


Fan Drive


Radiator


Water Pump


Cooling System Leaks
NO

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator


Batteries / Cables


Battery Compartment


Lighting


Starter


Wiring


Block Heater
YES
Cord in cab.

HYDRAULICS

Controls-Hydraulic


Controls-Travel & Steering


Cylinder Pins & Bushings


Cylinder pins / bushings.


Hydraulic Oil Lines & Tubes


Hydraulic Operating Condition


Lift Cylinders



Pump & Valves



Ride Control Operation



Self Leveling



Tank Hydraulic



Tilt Cylinder



Travel Drive Motors



Hydraulic System Leaks

NO

BUCKET

Coupler Pins & Bushings



Loader Frame



Loader Pins & Bushings



Coupler Quick Disconnect

YES

Hydraulic Quick coupler

Bucket S/N

A4225BK21601

Notes - BUCKET

74" GP Bucket

UNDERCARRIAGE

axles



Drive Sprockets



Idlers



Roller



Roller Frame



Track / Belt Condition



Track Adjuster



Notes - UNDERCARRIAGE

Part# 607-4803

Percentage Worn

Remaining : (L) 32/32 (R) 32/32.

99% - 99%

Track / Belt Width

320MM rubber track.

COMMENTS, MISC. REPAIRS, GENERAL REMARKS

comment 1

27

Inspected 2/10/26 at 41 hours.

MARKETING PHOTOS (21)







