

2019 CAT 226D SKID STEER LOADERS

INSPECTION DETAILS

Inspection Type	Marketing
Inspection Form	Standard
Inspection #	10267774
Inspection Status	Completed
Created	02/02/26 15:50:27
Updated	02/04/26 07:41:45
Created By	Garcia, Jr
Inspector	Garcia, Jr
Reviewers	Garcia, Jr
Salesperson	Schultis, Derrick R.
Stock #	E213067
Serial #	HRD04267
SMU / Hours	1,823
Location	Eloy , AZ, United States




FEATURES


General

- **Auxiliary Hydraulics Flow - Standard Flow**
- **Lighting**
- **Auxiliary Hydraulics Pressure - Low Pressure**
- **Product Link**
PRODUCT LINK, CELLULAR PL641
- **Coupler Type - Mechanical**
- **ROPS - Open**

Attachments

- **Bucket**

CONDITION Good Fair Poor Approved Repair**GENERAL CONDITION**Body
Frame
General
ET Product Status Report
Download
YESLogged / Active Codes
NOMachine Starts and is Operable
YESTires are Aired Up and Drivable
YESVisible Oil Leaks
YES**GENERAL APPEARANCE**Bumper
Cab or Canopy

CanopyCrankcase Guard / Battery Box
Decals
Eng. Enclose Hood / Stack
Fenders
Fuel Tank
Grab Irons
Main Frame Welds
Paint
Pre-Cleaner Bowl
Radiator Grill & Shroud
Sheet Metal
Steps / Ladder
**SAFETY ITEMS**Back Up Alarm
Dead Engine Lowering Valve
 1Horn


ROPS


Safety Locks / Pins


2 
Seat Belt / Date
January 2026

1

Parking Brake Functioning
YES

ROPS Certification Plate
YES

Safety Decals In Place
YES

Safety Decals Legible
YES

OPERATOR STATION

Armrests


Dash Console


Floor Boards / Mats


Gauges


Hour Meter - GAUGES,
OPERATION STATION, CONSOLE

1821 hours

1 
Hydraulic Controls


Interior Lights


Interior Plastic / Fabric


Mirrors


Monitoring Display


Seat Cushions / Suspension /
Type


1 
Switches


1

Windows


Current O&MM
YES

Current Parts Manual
YES
Cd

Current Safety Manual
YES

Fuel Level - OPERATOR STATION 
50%

ENGINE

Belts / Pulleys - ENGINE


Engine Oil Level / Condition


Engine Supports / Mounts


Exhaust / Muffler / Stack


Fuel Injection System


Governor


Intake / Air Filters


Operating Condition - ENGINE


Turbocharger / Blower


Apparent Other Engine Damage
NO

Blow By
NO

Emissions Decal Legible
NO

Fuel Leaks
NO

Knocking
NO

Oil Leaks
NO

Pre Lube System
NO

Service Needed
NO

Water in Oil
NO

36 hours on oil

Engine S/N
C8309011

Hours On Engine
1821 Hours

 1 Oil Pressure (H/L/N)
Normal

Smoke (B/D/L/W)
Normal

COOLING SYSTEM

Anti-Freeze Level / Color /
Condition

Red

Belts / Pulleys - COOLING
SYSTEM


Coolers


Fan


Fan Drive / Type


Fan Shrouds / Guards


Hoses & Tubes


Radiator


Water Pump


Compression in Radiator
NO

Coolant Leaks
NO

Oil in Anti-Freeze
NO

Standard Radiator
YES

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator



Batteries / Cables / Master

Disconnect



Lighting



Front aftermarket lights not working and right rear taillight lens is broken

Starter



Wiring



Front lights are aftermarket with wires nuts

TANDEMS/GEARS/BEARINGS/CHAINS

Front Axle



Lines / Linkages



Operating Condition -
TANDEMS/GEARS/BEARINGS/CH

AINS



Rear Axle



Travel Controls



Travel Motors



Travel Pumps



HYDRAULICS

Detent Switch



Hose Lines



Lift Cylinders



Operating Condition -
HYDRAULICS



Pumps & Valves



Tank



Tilt Cylinder



Leaks - HYDRAULICS

NO

BUCKET

Bucket Bottom



Bucket Linkage



Bucket Sides



Cutting Edges



Loader Frame



Loader Pins & Bushings



Quick Coupler



Manual

Bucket Capacity

No tags 61"

TIRES

	Make / Serial#	Tread Depth in 1/32"	% Life Remaining	Recapped	Tread Cuts/Chunks	Side Cuts Section
Left Front	Camso	8	33.33	NO	YES	NO
Left Rear	Camso	6	25.00	NO	YES	NO
Right Front	Camso	8	33.33	NO	YES	NO
Right Rear	Camso	6	25.00	NO	YES	NO

Spare

NO

Notes - TIRES

All tires are below 50%

Tire Size - TIRES

10-16.5. NHS

MARKETING PHOTOS (30)





